

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA F	
FILE	
U.S.G.S	
LAND FICE	
OPE OR	

RECEIVED NEW MEXICO OIL CONSERVATION COMMISSION

MAR 23 1976

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

O. C. C.
ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

<input type="checkbox"/> OIL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dry Hole		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> 5. State Oil & Gas Lease No. L-731
1. Name of Operator Cities Service Oil Company		7. Unit Agreement Name
3. Address of Operator Box 1919 - Midland, Texas 79701		8. Name of Lessee Name State CR Com.
4. Location of Well UNIT LETTER B 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 16 TOWNSHIP 21S RANGE 27E NMPM.		9. Well No. 1
15. Elevation (Show whether DF, RT, GP, etc.) 3248' GR		10. Field and Pool, or Wildcat Burton Flat Morrow
12. County Eddy		

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
---	--	---	--

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, in 100 word estimated limit. If any proposed work) SEE RULE 1103.

T.D. 11721' Shale PBTD 9635'. This well was plugged and abandoned in the following manner:

1. MIRU pulling unit, displaced hole w/250 bbls salt gel mud and pulled tubing.
2. Shot off 5-1/2" casing @ 8288' and pulled 199 Jts. out of hole.
3. Ran 2-7/8" OD open ended tubing and loaded hole w/150 bbls salt gel mud.
4. Displaced a 60 sack cement plug @ 8384 - 8234' (1/2 in and 1/2 out of 5-1/2" casing stub @ 8288').
5. Displaced a 60 sack cement plug across top of 2nd Bone Springs Sand @ 7100 - 6950'.
6. Displaced a 60 sack cement plug across top of 1st Bone Springs Sand @ 6350 - 6200'.
7. Displaced a 60 sack cement plug across top of Bone Springs @ 5175 - 5025'.
8. Displaced a 40 sack cement plug @ 3050 - 2950' (1/2 in and 1/2 out of 9-5/8" casing shoe @ 3000').
9. Spotted a 10 sack cement surface plug @ 58 - 0' and installed a 4" dry hole marker extending 4' above the ground to designate a plugged and abandoned location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *E. J. Miller*

TITLE **Region Operation Manager**

March 19, 1976

APPROVED BY *Robert Weems*

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: