

Submit 3 Copies
To Appropriate
District Office
DISTRICT I
1625 N. French Dr., Hobbs, NM 88240

DISTRICT II
811 South First, Artesia NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

CIBP

Form C-103
Revised March 25, 1999

WELL API NO. 30-015-21758
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K06527
7. Lease Name or Unit Agreement Name: Eddy "FV" State
8. Well No. 1
9. Pool name or Wildcat Penlon Bone Spring East
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:
Oil Well Gas Well Other

2. Name of Operator
PREMIER OIL & GAS, INC.

3. Address of Operator
P.O. Box 1246, Artesia, NM 88210

4. Well Location
Unit letter H : 1980 feet from the North line and 990 feet from the East line
Section 25 Township 20S Range 27E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK
- TEMPORARILY ABANDON
- PULL OR ALTER CASING
- OTHER:
- PLUG AND ABANDON
- CHANGE PLANS
- MULTIPLE COMPLETION

SUBSEQUENT REPORT OF:

- REMEDIAL WORK
- COMMENCE DRILLING OPNS.
- CASING TEST AND CEMENT JOB
- ALTERING CASING
- PLUG AND ABANDONMENT
- OTHER: Temporarily Abandon

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Premier wishes to hold this well in a temporarily abandoned status for future development.

The following work was done to hold this well in a TA status:

1. Set CIBP @ 6270'; cap w/35' cement.
2. Pressure test well to 1000 psi. See attached chart.

This Approval of Temporary Abandonment Expires 10/2005



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Koslie Jones TITLE President DATE 10/11/00

Type or print name _____ Telephone No. _____

(This space for State use)
APPROVED BY [Signature] TITLE Field Rep I DATE 10-18-00
Conditions of approval, if any: _____