

10. Restoration of Surface: If well is productive, pits will be backfilled and leveled as soon as practical. The plastic pit liner will be placed in the bottom of the pit before backfilling. Upon final abandonment the well site will be leveled and cleaned and the road ripped, with land returned as near as practical to original condition.
11. Operator's Representatives: Field personnel who can be contacted concerning compliance of this Surface Use Plan are as follows:

Drilling and Production: ~~Norman B. Ross~~ *Johnny Mc Donald*  
401 Wall Towers West  
Midland, Texas 79701

Office Phone - (915) 682-3711  
Home Phone - (915) 362-7658

12. Certification:

I hereby certify that I have inspected the proposed drill site area and access route; that I am familiar with the conditions as they actually exist; that the statements made in this plan are, to the best of my knowledge, true and correct; and that the proposed work performed by Northern Natural Gas Company and its contractors and sub-contractors will conform to this plan.

1-26-70  
Date

N.B. Ross  
N. B. Ross, Director, Engineering