

COPIES RECEIVED	3
DISTRIBUTION	
DATE	1
TIME	1
BY	
TO OFFICE	
REASON	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

JUN 28 1978

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO PLUG OR TO ABANDON OR TO PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO PLUG OR TO ABANDON FOR SUCH PROPOSALS.

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER Dry Hole

2. Name of Operator Harvey E. Yates Company

3. Address of Operator P. O. Box 1933, Roswell, New Mexico 88201

4. Location of Well

5. NEAREST CORNER K 1980 FEET FROM THE South 1980 FEET FROM West 7 20S 27E N.M.P.M.

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name Singer-Davis

9. Well No. 1

10. Field and Pool, or Wildcat McMillan morrow

12. County Eddy

11. Elevation (Show whether DF, RT, GR, etc.)
3335.8' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

☐ REINFORCED WORK	☒ PLUG AND ABANDON	☐ REINFORCED WORK	☐ ALTERING CASING
☐ CHAIRLY ABANDON	☐ CHANGE PLANS	☐ COMMENCE DRILLING OPS.	☐ PLUG AND ABANDONMENT
☐ CH ALTER CASING	☐	☐ CASING TEST AND CEMENT JOBS	☐
☐	☐	☐ OTHER	☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We intend to plug and abandon this well in the following manner:

Plug #1 - Top Morrow - 25 Sx at 10,250'
Plug #2 - Strawn - 25 Sx at 9100'
Plug #3 - Wolfcamp - 25 Sx at 8000'
Plug #4 - Bone Springs - 25 Sx at 6200'

1st Plug - 9403 - 10,240 - 25 SX
2nd Plug - 8767 - 9105 - 25 SX
3rd Plug - 7662 - 8000 - 25 SX
4th Plug - 5882 - 6220 - 25 SX
CIBPE 5550 ±
BW 6/30/78

The following plugs to be determined by amount of 4 1/2" casing recovered. If casing free and shot off at ± 5500' spot 40 Sx plug 50' in and 50' out of casing stub.

Plug #6 - 40 Sx at 2800'
Surface plug - 10 Sx

4 1/2" shot + pulled from 5500's
spotted 40 Sx @ 5535' 7/1/78
spotted 40 Sx @ 2800' mw

Install dry hole marker on top.

Clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Peck Harder TITLE Engineer DATE June 27, 1978

VIC BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE JUN 29 1978

REMARKS OF APPROVAL, IF ANY: Intervals between plugs filled with mud

Notify N.M.O.C.C. in sufficient time to witness Plugging