

Surface

Bravo Oper.

Mesa Macho #2

24-20-27

Danell  
~~Morse~~

4/2/92

Plug @ shoe  
710-610  
Tag

13 3/8 @ 660' Circ.

Mud between  
Plugs

100' or 25 sx of cmt.  
whichever is greater

Plug at shoe  
2650-2550  
Tag

9 5/8 @ 2600' Circ

Del. 2700

Plug at BS  
4732-4632

BS 4682

Plug @ 2nd SS  
6280-6180

2nd SS 6230

Plug @ WC  
8770-8670

Not on Johnny's

WC 8720

Stub Plug  
9270-9370  
Tag

TOC 9320 Temp. Survey

Plug @ Penn  
9630-9530

Penn 9580

Strawn 9995

Plug at Atoka  
10270-10370

Not on Johnny's

Atoka 10320

Morrow 10740

CIBP w 35' cmt  
at 11200  
Tag

Penta 11242-11250

5 1/2 @ 11430'

