

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED
FEB 11 1992

O. C. D.
ARTESIA OFFICE

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L326
7. Lease Name or Unit Agreement Name Lone Tree
8. Well No. 1
9. Pool name or Wildcat Undesignated Bone Spring
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 3163

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Bledsoe Petro Corporation ✓
3. Address of Operator 3908 N. Peniel, Suite 500, Bethany, OK 73008
4. Well Location Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line Section 13 Township 21S Range 27E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Loaded hole with 9.3# mud
Pump 100' cement plug from 2900-2800
Pump 100' cement plug from 1250-1150
Pump 100' cement plug 650-550
pump 30' plug at surface
Cut off and weld plate on 9 5/8" casing, put on 6' well marker

Post ID-2
2-14-92
PxA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tom Conroy TITLE Engineer DATE 2/6/92
TYPE OR PRINT NAME Tom Conroy TELEPHONE NO. _____

(This space for State Use)

APPROVED BY Mike Sturges TITLE Field Rep. DATE June 25-92

CONDITIONS OF APPROVAL, IF ANY: