

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other PLUGGED AND ABANDONED	5. Lease Designation and Serial No. NM-886-A
2. Name of Operator YATES PETROLEUM CORPORATION	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. 105 South 4th St., Artesia, NM 88210	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1930' FSL & 2080' FEL, Sec. 11-T21S-R21E	8. Well Name and No. El Paso Federal GS #1
	9. API Well No. 30-015-21973
	10. Field and Pool, or Exploratory Area Box Canyon Permo Penn
	11. County or Parish, State Eddy, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

CONTINUED FROM PREVIOUS PAGE:

2-15-95 - TIH with tubing and tagged top of cement at 3037'. Loaded hole. Spotted 34 bbls plug mud from 3037-1600' (in 5-1/2" casing). POOH with tubing. Nippled down wellhead & BOP. Rigged up welder. Welded 5-1/2" pull nipple on. Pulled slips. Rigged down casing equipment. Nippled up BOP and wellhead. TIH with tubing to 1714'. Mixed and pumped 60 sacks Class C cement from 1714-1497'. POOH with 2-3/8" tubing. Shut down for night.
2-16-95 - TIH with tubing and tagged top of cement at 1660'. Mixed and pumped 50 sacks Class C cement with 2% CaCl₂ from 1660-1497'. POOH with tubing. WOC 3-1/2 hours. TIH with tubing and tagged top of cement at 1530'. Mixed and pumped 10 sacks Class C cement from 1530-1495' (in 8-5/8" casing). POOH with 2-3/8" tubing at 1490'. Spotted 90 bbls plug mud from 1490' to surface. POOH with tubing to 50'. Mixed and pumped 50 sacks Class C cement from 50' to surface. POOH and laid down tubing. Nippled down BOP. Cleaned location and installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT.
Plugging completed 2-15-95.

14. I hereby certify that the foregoing is true and correct

Signed *Rusty Klein* Title Production Clerk Date Feb. 27, 1995

(This space for Federal or State office use)

Approved by _____ Title _____ Date _____
Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side