## Submit 3 Copies to Appropriate District Office

Type of Well:

11.

P.O. Box 1980, Hobbs, NM 88240

P.O. Drawer DD, Artesia, NM 88210

DISTRICT I

## E

rorm (	-1W
Revised	1-1-8

	State of them taleation
nergy, M	-als and Natural Resources Departmen

OIL	CONSI	ERVA'	TION	DIVISIO	)N
			~~~		

P.O. Box 2088; FIVED Santa Fe, New Mexico 87504-2088

AUG 2 6 1993

WELL API NO. 30-015-22002	1
5. Indicate Type of Lease STATE X	FEE

STRICT III	
00 Rio Brazos Rd., Aztec, NM 87410	0.00

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Feet From The

Eddy

SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Stonewall EP State 8. Well No.

GAS WELL X WELL 2. Name of Operator YATES PETROLEUM CORPORATION 3. Address of Operator

9. Pool name or Wildcat 105 South 4th St., Artesia, NM 88210 Burton Flat Morrow

4. Well Location Unit Letter .

660 Feet From The \_\_

20S Range

South

28E

Line and 1980

County

Section

PERFORM REMEDIAL WORK

**PULL OR ALTER CASING** 

Township 10. Elevation (Show whether DF, RKB, RT, GR, etc.)

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF:

NOTICE OF INTENTION TO:

REMEDIAL WORK PLUG AND ABANDON

**ALTERING CASING** 

TEMPORARILY ABANDON

**CHANGE PLANS** 

COMMENCE DRILLING OPNS.

PLUG AND ABANDONMENT

OTHER: Add perforations in Morrow

CASING TEST AND CEMENT JOB OTHER:\_

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed

work) SEE RULE 1103. Propose to add pay in the Morrow Sand from 10952-10959' and 11005-11016! as follows:

- Install standing valve in on/off tool at 11031'. Load tubing with fluid. Test tubing 2500 psi. Test annulus to 500 psi. Nipple up BOP and get off on/off tool. TOOH with tubing.
- Rig up Vann and tubing convey perforate the Morrow from 10952-10959' and 11005-11016' as follows: 10952-10959'; 11005-11008' and 11012-11016' with 4 SPF.
- Set packer and test annulus to 1000 psi. Nipple up tree.
- Test well.

I hereby certify that the inform	nation above is true and complete to the best of my knowled	ige and belie			
SIGNATURE HUS	ty Blein	mle _	Production Clerk	DATE Aug.	25, 1993
TYPE OR PRINT NAME	Rusty Klein			TELEPHONE NO.	505/748-1473
(This space for State Use)	ORIGINALISIGNED BY MIKE WILLIAMS			SEP	— 7 19 <b>93</b>
	SUPERVISOR, DISTRICT II			DATE	

CONDITIONS OF APPROVAL, IF ANY: