

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED
OMB No. 1004-0135
February 31, 1996

N.M. Oil Cons. Division

811 S. 1st Street

Artesia, NM 88210-2834

Lease Serial No. NM 15003

Well Name and No.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

OXY USA INC. ✓

16696

3a. Address

P.O. BOX 50250
MIDLAND, TX 79710-0250

3b. Phone No. (include area code)

915-685-5717

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2105 FSL 760 FWL NWSW(4) Sec 9 T20S R28E

7. If Unit or CA/Agreement Name and/or No.

8. Well Name and No.

Government AB #4

9. API Well No.

30-015-22019

10. Field and Pool, or Exploratory Area

Burton Flat Morrow

11. County or Parish, State

Eddy NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

See other side



14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

DAVID STEWART

Title

REGULATORY ANALYST

Signature

David Stewart

Date

12/20/00

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

(ORIG. SGD.) ALEXIS C. SWOBODA

Title

PETROLEUM ENGINEER

Date

DEC 22 2000

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

GOVERNMENT AB #4

TD-11290' PBSD-11240' PERFS-10965-11056' 10406-10800' (BO) PKR-10843'

13-3/8" 54.5# CSG @ 600' W/ 550sx, 17-1/2" HOLE, TOC-CIRC
8-5/8" 24-32# CSG @ 3015' W/ 1700sx, 12-1/4" HOLE, TOC-SURF
5-1/2" 17-20# CSG @ 11290' W/ 750sx, 7-7/8" HOLE, TOC-8190'-TS

1. RIH & SET CIBP @ 10915', DUMP 5sx CMT TO 10880', WOC-TAG
 2. RIH & SET CIBP @ 10356', DUMP 5sx CMT TO 10321', WOC-TAG
 3. M&P 25sx @ 9811-9711'
 4. M&P 25sx @ 9003-8903'
 5. PERF @ 6403', SQZ W/ 35sx TO 6303', WOC-TAG
 6. PERF @ 4730', SQZ W/ 35sx TO 4630', WOC-TAG
 7. PERF @ 3065', SQZ W/ 35sx TO 2965', WOC-TAG
 8. PERF @ 1240', SQZ W/ 35sx TO 1140', WOC-TAG
 9. PERF @ 650', SQZ W/ 35sx TO 550', WOC-TAG
 10. M&P 10sx CMT SURFACE PLUG
- 10# MLF BETWEEN PLUGS

RECEIVED
10 DEC 21 12 00 PM

RECEIVED

RECEIVED

OXY USA INC. PROPOSED
GOVERNMENT AB 4
SEC 9 T20S R28E EDDY NM

