

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB No. 1004-0135  
Expires July 31, 1996

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

N.M. Oil Cons. Division  
811 S. 1st Street  
Alamogordo, NM 88210-2834

SUBMIT IN TRIPLICATE - Other Instructions on reverse

1. Type of Well  
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
OXY USA INC. 16696

3a. Address P.O. BOX 50250  
MIDLAND, TX 79710-0250 3b. Phone No. (include area code)  
915-685-5717

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
2310 FNL 660 FWL SWNW Sec 27 T21S R27E

5. Lease Serial No. NM-103796  
6. If Indian, Allottee or Tribe Name  
7. Unit or CA/Agreement, Name and/or No.  
8. Well Name and No.  
Government A0 #2  
9. API Well No.  
30-015-22020  
10. Field and Pool, or Exploratory Area  
Undesignated Atoka  
11. County or Parish, State  
EDDY NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

See other side

Last Well On Lease. Lease NM-103796  
Will Terminate In 60 Days (03-21-2000)  
Without Operations To Restore Production.

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

DAVID STEWART

Title

REGULATORY ANALYST

Signature

Date

1/18/00

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

(ORIG. SGD.) DAVID R. GLASS

Title

PETROLEUM ENGINEER

Date

JAN 21 2000

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

SEE ATTACHED FOR  
COMMITTEE OF APPROVAL

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

OXY USA INC.  
GOVERNMENT AD #2  
SEC 27 T21S R27E  
EDDY COUNTY, NM

TD - 11815'      PBSD - 10485'      PERFS - 10355-10446'

CASING:      13-3/8" 54.5# @ 602', 17-1/2", cmt w/ 700sx, TOC-CIRC  
              8-5/8" 24-32# @ 3020', 12-1/4", cmt w/ 3085sx, TOC-CIRC  
              5-1/2" 17-20# @ 11815', 7-7/8", cmt w/ 800sx TOC-8262'-CBL

1.      RIH & SET CIBP @ 10305', DUMP 5sx CMT TO 10270'
2.      M&P 25sx CMT @ 9555-9455'
3.      CUT & PULL 5-1/2" CSG AT ABOUT 8250'
4.      M&P 35sx CMT @ 8300-8200'
5.      M&P 45sx CMT @ 6200-6100'
6.      M&P 45sx CMT @ 5200-5100'
7.      M&P 40sx CMT @ 3070-2970'
8.      M&P 35sx CMT @ 652-552'
9.      M&P 20sx CMT SURFACE PLUG
- 10# MLF BETWEEN PLUGS

RECEIVED  
JUN 19 1967

RECEIVED  
JUN 19 1967

RECEIVED