

August 26, 2002

Oil Conservation Division 1301 W Grand Artesia, NM 88210

Attn: Van Barton

Re: Hunker Com #1 K-35-21S-27E API 30-015-22086



Dear Van:

In response to your letter dated August 17 regarding a packer leakage test on the above well, I am enclosing a diagram of the mechanics. This well is a dual producer from the Morrow and Wolfcamp. The Morrow has been plugged off since 1978. This completion was approved by the OCD. The well flows from the perforations thru the packer out to crossover into the casing. It then flows out casing to surface.

If this test is required, a workover would have to be performed.

Please advise.

Sincerely,

Carroll Bellah

ONBellal