

NEW MEXICO OIL CONSERVATION COMMISSION

C. E. G.  
PORTLAND, OREGON

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
30-015-22114	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Texas Oil & Gas Corp. ✓	8. Farm or Lease Name Rayroux Com
3. Address of Operator 900 Wilco Building, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER K, 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 19, TOWNSHIP 21-S, RANGE 27-E NMPM.	10. Field and Pool, or Wildcat Undes. Morrow
15. Elevation (Show whether DF, RT, CR, etc.) 3151' DF	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY SHUT-IN <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PLUG AND ABANDON PROCEDURE

Plug #1 - CIBP @ 10900' w/35' cmt on top 10870 - 10839  
 Plug #2 - CIBP @ 9800' w/35' cmt on top 9765 - 9730  
 Enter - Recover 4 1/2' csg from approx. 7900' 7860  
 Plug #3 - 40 sx cmt plug - 7900' or 4 1/2" csg. stub 7719 - 7569  
 Plug #4 - 40 sx cmt plug - 6000' 4861 - 4721  
 Plug #5 - 40 sx cmt plug - 4850' 2745 - 2645  
 Plug #6 - 50 sx cmt plug - 2800'  
 Plug #7 - Surface plug & marker

By [Signature] 3-17-18-20-78

AS PER TELEPHONE CONVERSATION 12-7-77

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] (Cecil Pearce) TITLE Drilling Foreman DATE 12-12-77

APPROVED BY [Signature] TITLE [Signature] DATE 12-17-77

CONDITIONS OF APPROVAL, IF ANY:  
Load hole w/ mud Plugging