NO. OF COPIES RECEIVED		3
DISTRIBUTION	<u> </u>	
SANTA FE		L
FILE	1/	1
u.s.g.s.		<u> </u>
LAND OFFICE		<u> </u>
OPERATOR	1/	

RECEIVED

Form C-103 Supersedes Old

NO. OF COPIES RECEIVED	<u></u> ₽	見た は	E i A E P	Superseaes Cha	
DISTRIBUTION		NEW MEXICO OIL CONSERVATION COMMISSION		C-102 and C-103 Effective 1-1-65	
SANTA FE	7 N	EW MEXICO OIL CONSE	RVATION COMMISSION	Effective 1-1-0.	3
FILE	110	APK	1 8 1978	5a. Indicate Type	of Lease
U.S.G.S.				State 🛣	Fee.
LAND OFFICE		f ⁻⁷ 1	prej	Sidle E	•
OPERATOR	-/- -1		NA, OFFIGE	5. State Oil & Gas Lease No. , 30-015-22114	
OF ENATION		7.27		30-013 2	TTTTTTTTTT
	SUNDRY NOTICES	S AND PEPORTS ON	WELLS		
(DO NOT USE THIS FOR	M FOR PROPOSALS TO DAL	LL OR TO DEEPEN OR PLUS BA	WELLS CK TO A DIFFERENT RESERVOIR. PROPOSALS.)	UIIIIII	711111111
	APPLICATION FOR PERMIT			7. Unit Agreement	, Name
l. GAS	X other.				
WELL WELL	. L. OTREAT			8. Farm or Lease	
2. Name of Operator	Gas Corp 🧪			Rayroux (Cer.
				9. Well No.	
3. Address of Operator	ulda Midland (πx √79701		1	
	ldg, Midland,	IN 75701		10. Field and Poo	ol, or Wildcat
4. Location of Well	1000	couth	1980	Undesign	ated (Morrow)
K	198U FE	ST FROM THE	LINE AND FEET FRO	mmm "	HHHHH
UNIT LE, TEN		27	c 27 – F'		
west	19	ZITA TOWNSHIP	S 27-E NMPI	w (////////	
THE				12. County	7////////
mmmm	1 1111111	5. Elevation (Show whether	DF, RT, GR, etc.)	Eddy	
		3151' 1	DF'	Eddy	(11111111111111111111111111111111111111
(1):////////////////////////////////////	Cl. 1 Assessment	o Boy To Indicate N	Nature of Notice, Report of C	ther Data	
	Check Appropriat	E DOX TO Midicate IV	subseque!	NT REPORT OF:	
NOTI	CE OF INTENTION	10:			
-	1	PLUG AND ABANDON	REMEDIAL WORK	ALTER	RING CASING
PERFORM HEMEDIAL WORK		PLUG AND ABANDON	COMMENCE DE LLING OPNS.	PLUG .	AND ABANDONMENT
TEMPOPARILY ABANDON	<u>.</u>		[
PULL OR ALTER CASING		CHANGE PLANS	CASING TEST AND CEMENT JOB		
		_	OTHER		
OTHER					
		Destinant dat	tails, and give pertinent dates, includ	ing estimated date of	starting any propose
17. Describe Proposed or C work) SEE RULE 1003.	ompleted Operations (Cl	early state all pertinent uel	atts, unit give portion		
work) SEE ROLL 1100.			_		nn a 10 000!
3-18-78	Released pki	c. POH w/tbg & pk	cr. Dumped 35' cement	on top of Cir	3P @ 10,900 .
3 2 •	Cot CIPD on	ыт a 9812' Dum	nped 35' cmt on top of	CIBP @ 9012	•
3-19-78	a 1 17.11	a 7000! Tinahle	a to free csa. Cut CS9	' @ //U9 - r	reed cag.
3 13 70	Cira holo w	/miid @ 7709!. St	potted Plug #1 40 sxs $arphi$	lass n prug .	1100 1000 .
	D. 17 - 4 agg :	to cond! - Spotte	ed 40 sxs cmt blug Irou	1 6000 60 30	00.
2 21 70	Pulled csg to 6000' - Spotted 40 sxs cmt plug from 6000' to 5860'. POH w/remainder of 4½ csg. RIH w/2-3/8" tbg to 4861'. Spotted 40 sxs cmt plug from 4861' to 4721'. POH w/tbg to 2795' - Set 50 sxs plug from				
3-21-78	emt plug fr	om 4861' to 4721'	'. POH w/tbg to 2795'	- Set 50 sxs	plug from
	CML prug 11	4E! DOU 1/22	Set 15 sxs cmt surfac	e plug.	
	2/95° to 26	Thank FOR W/ CDg.	n surface plate & dry h	ole marker.	
			1 surrace prace a dry		
	JOB COMPLET	E	the delegate word and words	ve nit clea	red and
4-7-78	Removed and	disposed of call	iche drlg pad and reser	AE DICL CTCH	

		the best of my knowledge and belief.		
18. I hereby certify that the information	above is true and complet	e to the best of my knowledge and belief.		
(1 is four to	Cecil Pearce	TITLE Drilling Superintendent	DATE	4-12-78
SIGNED COLOR				
	N 1			1111 9 c 1978

cleaned location.