

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well

☐ Gas Well

☒ Other

Plug & Abandon Well

2. Name of Operator

YATES PETROLEUM CORPORATION

(505) 748-1471

3. Address and Telephone No.

105 South 4th St., Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit J, 1980' FSL, 1980' FEL, Sec. 14-T21S-R21E

RECEIVED

JAN 12 1992

O. C. D.
ARTESIA OFFICE

5. Lease Designation and Serial No.

NM 8417

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Box Canyon #3

9. API Well No.

30-015-22194

10. Field and Pool, or Exploratory Area

Box Canyon Permo-Penn

11. County or Parish, State

Eddy, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to plug and abandon well as follows:

Set CIBP at 5575' w/35' Class "H" cement.

Run freepoint (est. TOC @ 3500'). Shoot casing off approx. 100' above freepoint with casing cutter. TOOH and laydown casing. Keep hole full 9.0 ppg mud.

Spot plug 3450-3350' w/50 sx Class "C" Neat cement plug across 5-1/2" casing stub (50'in/50' out). (9.0 ppg mud behind cement to spot plug.) Tag plug.

Spot plug 1180-1075' w/60 sx Class "C" Neat cement across 8-5/8" casing shoe. Tag plug.

Spot 37' to surface w/10 sx Class "C" Neat cement.

Set regulation abandonment marker.

NOTIFY BLM, CARLSBAD, NM AND NMCD, ARTESIA, NM, 24 HRS BEFORE STARTING OPERATIONS SO THEY CAN WITNESS JOB.

14. I hereby certify that the foregoing is true and correct

Signed

Title Production Supervisor

Date 10-22-91

(This space for Federal or State office use)

Approved by

Title

Date 1/8/92

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side