

RECEIVED

FEB 13 1992

CISF

Form 3160-5
(June 1990)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTO. C. D.
ARTESIA OFFICEFORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other P&A

2. Name of Operator

YATES PETROLEUM CORPORATION (505) 748-1471

3. Address and Telephone No.

105 South 4th St., Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit J, 1980' FSL, 1980' FEL, Sec. 14-T21S-R21E

5. Lease Designation and Serial No.
NM 8417

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Box Canyon #3

9. API Well No.

30-015-22194

10. Field and Pool, or Exploratory Area

Box Canyon Permo-Penn

11. County or Parish, State

Eddy, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐
- Notice of Intent
-
- ☒
- Subsequent Report
-
- ☐
- Final Abandonment Notice

TYPE OF ACTION

- ☒
- Abandonment
-
- ☐
- Recompletion
-
- ☐
- Plugging Back
-
- ☐
- Casing Repair
-
- ☐
- Altering Casing
-
- ☐
- Other

- ☐
- Change of Plans
-
- ☐
- New Construction
-
- ☐
- Non-Routine Fracturing
-
- ☐
- Water Shut-Off
-
- ☐
- Conversion to Injection
-
- ☐
- Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged and abandoned well as follows: Pump 30 bbls brine down tubing. Tried to release packer. Would not release. Talked to Jim Amos, BLM, Carlsbad, NM. Permission given to short tubing and set wireline CIBP above tubing stub.

Open well. Pumped 80 bbls brine into perfs. Kill well. Jet cut tubing at 5580'.. Set CIBP at 5572'. Pumped 140 bbls brine laden mud and capped CIBP w/15 sacks. POH with tubing. Stood 55 stands in derrick. Laid rest of tubing down. NDBOP. Dug out cellar below bradenhead. Opened backside of 5-1/2". Cut wellhead bolts off. Pulled 5-1/2" packing out of well. Pulled 185,000 to get 5-1/2" flips out of wellhead. Worked pipe. Had 2500' free. Called Cathy, BLM, Carlsbad. Cut casing around 2500'. RIH with jack cutter. Cut casing at 2550'. Pulled total 60 joints. RIH and spot plug at 2583'. Tag plug at 2411'. Had 60' inside 5-1/2" casing. Had 112' above casing stub. Total fill of plug 172'. Pull up hole to 1180'. Spot 60 sx cement plug w/2% CaCl2. Pull up hole 14 stands and wait on cement 4 hrs. Did not tag plug. Spot 60 sx cement plug w/3% CaCl2. WOC. Tag plug at 1070' - 56' of fill over 8-5/8" shoe. Jim Amos approved plug. Mixed mud from 1070' up. Pull up hole to 60' from surface. Pumped 20 sx cement plug @ surface. RD. Installed dry hole marker. Plugging completed 1-26-92.

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.Post ID-2
2-14-92
PVA

14. I hereby certify that the foregoing is true and correct

Signed

Title Production Supervisor

Date 2-4-92

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side