

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
----------------------------	--------------------------------	---

5. State Oil & Gas Lease No.

7. Unit Agreement Name	None
------------------------	------

8. Farm or Lease Name	Pardue Farms
-----------------------	--------------

9. Well No.	1
-------------	---

10. Field and Pool, or Wildcat	Wildcat Morrow
--------------------------------	----------------

12. County	
------------	--

15. Elevation (Show whether DF, RT, GR, etc.)	3680 GR
---	---------

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
--

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
--

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.
--

Original Signed by	Jerry C. Buckles
--------------------	------------------

TITLE	Area Supervisor
-------	-----------------

DATE	March 30, 1978
------	----------------

APPROVED BY	Mike Stapp
-------------	------------

TITLE	OIL AND GAS INSPECTOR
-------	-----------------------

DATE	SEP 14 1978
------	-------------

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/>	GAS WELL <input checked="" type="checkbox"/>	OTHER- <input type="checkbox"/>
--------------------------------------	--	---------------------------------

2. Name of Operator	Anadarko Production Company
---------------------	-----------------------------

3. Address of Operator	P. O. Box 67, Loco Hills, New Mexico 88255
------------------------	--

4. Location of Well	UNIT LETTER F 2130 North 1980
---------------------	-------------------------------

West 27 21S 24E	THE LINE, SECTION TOWNSHIP RANGE NMPM.
-----------------	--

15. Elevation (Show whether DF, RT, GR, etc.)	3680 GR
---	---------

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
--

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
--	---

TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
--	---------------------------------------

PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>
---	--------------------------------

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
--	---

COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
--	---

CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>
--	--------------------------------

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
--

1. Rigged up pulling unit. ID 9853

2. Ran 4 1/2" wireline CIBP, set @ 7603'.

3. Shot off 4 1/2" casing @ 7070' and recovered 187 joints.

4. Went in hole with 2-3/8" tubing and pumped 35' (6 sack) cement plug - 7600-7565 on top of CIBP.
--

5. Pumped 26 sack cement plug 7120-7020 (50' in and 50' out of 4 1/2" casing stub.
--

6. Pumped 40 sack cement plug 5400-5300 in Open Hole.

7. Pumped 40 sack cement plug 3750-3650 in Open Hole.

8. Pumped 40 sack cement plug 2650-2550 in Open Hole.

9. Pumped 40 sack cement plug 2050-1950 (50' in and 50' out of 9-5/8" casing stub.
--

10. Cut off 9-5/8" and 13-3/8" casing and salvaged wellhead equipment.
--

11. Pumped 18 sack cement plug from 20' to surface.

12. Erected P & A marker, cut off and removed all well service anchors, filled cellar, removed junk and equipment from location, covered all pits and leveled location to the original contour of the surface. Well plugged 2-27-78.
--

Note: Plugging operations were witnessed by Mr Weaver from the Artesia office of New Mexico Oil Conservation Commission.