

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-03677

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Harvey E. Yates Company		8. FARM OR LEASE NAME Stebbins Federal	
3. ADDRESS OF OPERATOR P. O. Box 1933, Roswell, N. M. 88201		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2970' FEL & 660' FSL		10. FIELD AND POOL, OR WILDCAT Wildcat	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 30, T-20S, R-29E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3236.68' GL		12. COUNTY OR PARISH Eddy	
		13. STATE N. M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETION <input checked="" type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11-10-77 We will plug and abandon as follows:

- Plug #1 - 100' plug (30 Sxs) @ 3209' KB (Above Delaware)
- Plug #2 - 100' plug (30 Sxs) @ 1132' KB (Top Capitan Reef)
- Plug #3 - 100' plug (30 Sxs) @ 820' KB (Top Yates)
- Plug #4 - 100' plug (30 Sxs) @ 603' KB (Top Salt)
- Plug #5 - 100' plug (30 Sxs) @ 389' KB (In and Out 8 5/8" Casing)
- Plug #6 - 30' plug (10 Sxs) @ Surface

4 1/2" pipe welded to plate over 8 5/8" casing stub for dry hole marker to be installed.

RECEIVED
NOV 23 1977
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED <u>Chick Harder</u>	TITLE <u>Engineer</u>	DATE <u>11-17-77</u>
(This space for Federal or State office use)		
APPROVED BY <u>Lee J. Linn</u>	TITLE <u>ACTING DISTRICT ENGINEER</u>	DATE <u>DEC 19 1977</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

DEC 11 1971

U.S. DEPT. OF JUSTICE