

UNITED STATES NMOC COPY
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 9187

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Box Canyon "4A"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 23-21S-21E
Unit B NMMP

12. COUNTY OR PARISH

Eddy

NM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4592' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

WIH w/perforating gun and perforated 6392-6412' w/20 .40" holes (2spf). No show of oil or gas. WIH w/Guiberson Uni-VI packer on 2-3/8" tubing, set packer at 6361' and treated perforations 6392-6412' w/2000 gallons of 15% DS-30 acid. Swabbed. Unable to swab down. Set Cast Iron Bridge Plug at 6050', dumped 1 bailer of cement on top of plug. WOC. WIH w/Wireline and perforated 5886-6019 1/2 w/48 .32" shots as follows: 5886, 87, 87 1/2, 88, 88 1/2, 90; 5926, 26 1/2, 28, 29, 30, 30 1/2, 32, 40, 41, 42, 42 1/2, 43, 43 1/2, 44, 44 1/2, 45, 45 1/2, 47, 48, 59, 61, 62, 62 1/2, 63, 63 1/2, 64, 64 1/2, 65, 82, 83, 84, 84 1/2, 85, 94, 94 1/2, 95, 95 1/2; 6017, 18, 18 1/2, 19, 19 1/2. WIH w/Guiberson Unit-VI packer on 2-3/8" tubing, set packer at 5862' and treated perforations w/3000 gallons 15% DS-30 acid and ball sealers. After well flowed back load and cleaned up - well flowed 525# on 3/4" choke = Rate 7.7 MMCFPD.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Geol. Secty

DATE 2-28-78

(This space for Federal or State office use)

APPROVED BY

TITLE ACTING DISTRICT ENGINEER

DATE MAR 6 - 1978

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED
MAR 1 - 1978
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO