Form 9-331 (May 1963)

UNITE STATES DEPARTMENT OF THE INTERIOR (Other interior werse side)

SUBMIT IN TRIPLICAT. instructions on re-

Form approved, Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

GEOLOGICAL SURVEY

NM-9531-B

| SUNDRY | NOTICES | AND | REPORTS | ON | WFIIS |
|--------|---------|--------------|---------|----|-------|
| | | ΔIII | | | ** |

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals RECEIVE 7. UNIT AGREEMENT NAME GAS WELL OTHER P & A JUN 3 0 1978 2. NAME OF OPERATOR 8. FARM OR LEASE NAME INEXCO OIL COMPANY <u> Majoros Federal</u> ADDRESS OF OPERATOR O. C. C. 77002 ARTESIA, DEFICE 1100 Milam Bldg. Suite 1900, Houston, TX 77002 ARTES LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface 10. FIELD AND POOL, OR WILDCAT, Morrow 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA NE 1/4,SE 1/4 Sec 23- T21S-R22E 1980' FSL & 810' FEL Sec 23-T2]S-R22E 12. COUNTY OR PARISH | 13. 8 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 13. STATE 4203' GR Eddy MM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

| NOT | ICE OF INTENT | ION TO: | | | SUBSEQUENT REP | orr of: | |
|---------------------------------|---------------|---------------------------|---|--|--------------------------------------|------------------------------|--|
| TEST WATER SHUT-OFF | | TLL OR ALTER CASING | | WATER SHUT-OFF | | REPAIRING WELL | |
| FRACTURE TREAT SHOOT OR ACIDIZE | | ULTIPLE COMPLETE BANDON* | X | SHOOTING OR ACIDIZ | _ i | ALTERING CASING ABANDONMENT* | |
| repair well (Other) Notice (| | to abandon | | (Other) (Νοτε: Repor Completion or | t results of mult Recompletion Re | dple completion on Well | |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Due to stuck drill pipe @ 1024', Inexco intends to plug and abandon this well by setting four stages consisting of 100 sx cmt in each stage, then set twelve stages consisting of 50 sx in each stage from 345' to 140'. Cut off casing at surface then set 20 sx class "C" from 0' to 37', weld plate on top and set dry hole marker.

RECEIVED

JUN 30 1978

U.S. BEULUGICAL SURVEY ARTESIA, NEW MEXICO

| (This space for Federal or State office use) | TITLE ACTING DISTRICT ENGINEER | DATE _ | 0.0 1070 |
|--|--------------------------------|--------|-------------|
| APPROVED BY SOL WALL CONDITIONS OF APPROVAL, IF ANY: | TITLE ACTING DISTRICT ENGINEER | DATE _ | JUN 30 19/8 |