STATE OF NEW MEXICO	
ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION	C C 101
DISTRIBUTION P. O. COM-2003	Form C-103 · Revised 10-1-78
SANTA FE, NEW MEGENEDS BY	Sa, Indicate Type of Lease
U.S.O.S. APR 4 1986	State X Foo .
LANO OFFICE	5. State Oil & Gas Lease No.
O. C. D.	K-5115
SUNDRY NOTICES AND REPORTS ON WEATHER, OFFICE	
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPUSALS.)	7. Unit Agreement Name
OIL GAS X OTHER-	
2. Name of Operator	8. Farm or Lease Name
Yates Petroleum Corporation V	Stonewall EP State Com 9. Well No.
3. Address of Operator 207 South 4th St., Artesia, NM 88210	4
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER H 1980 FEET FROM THE NORTH LINE AND 660 FEET FROM	Undės. Strawn
VALUE COLOR	
THE East LINE, SECTION 30 TOWNSHIP 20S RANGE 28E NMPM	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3260' GR	Eddy
16. Check Appropriate Box To Indicate Nature of Notice, Report or Ot	her Data
NOTICE OF INTENTION TO: SUBSEQUEN	T REPORT OF:
PERFORM REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE ORILLING OPNS.	PLUG AND ASANDONMENT
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	· · · ·
OTHER Abandon Morrow & Atoka; recomplete X	
	and description and proposed
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includin work) SEE RULE 1103.	g estimated date of starting any proposed
· · · · · · · · · · · · · · · · · · ·	
Propose to pull packers and guns from Atoka and Morrow completions	, set CIBP at 11100'
/25' coment on top to abandon Morrow and CIBP at 10530' W/35' cem	ient on top to abandon
Atoka, to perforate and stimulate Strawn at 10126-139', return wel	.i to production.
•	·
·	
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
	4-3-86
Production Supervisor	DAYE 4-3-00
Original Signed By	
Les A. Clements	APR 11 1986
Supervisor District II	

