

SOUTHLAND ROYALTY COMPANY
POST OFFICE BOX 520 • ROSWELL, NEW MEXICO 88201 • SOB, CASH
RECEIVED

ATTACHMENT FOR FORM C-104

SEP 24 1978

U.S. GEOLOGICAL SURVEY
ARIZONA, OFFICE

1

Southland Royalty Company suspended operations on this well late in 1978 after drilling a dry hole to the Morrow and plugging back to 2,500'. John H. Trigg re-entered and completed the Queen Formation.

2

Hole sizes on both the 13 3/8" surface pipe and the intermediate string of 3 5/8" have heretofore been filed by Southland Royalty Company, Midland, Texas, when this test well was drilled.