

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

415F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER Dry Hole

2. NAME OF OPERATOR
Nearburg Producing Company

3. ADDRESS OF OPERATOR
P. O. Box 31405 Dallas, Texas 75231

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
2310' FSL & 960' FEL of Section 11

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4016 GR

5. LEASE DESIGNATION AND SERIAL NO.
NM 12828

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
McKittrick Fed Com

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Und. Morrow

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 11, T-22-S, R-24-E

12. COUNTY OR PARISH
EDDY

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Dump 35' cement on existing CIBP @ 10,334'.
2. Set CIBP @ 10,200'. Dump 35 sacks cement on plug.
3. Cut and Pull 4½", 9,000 to surface.
4. Set 70 Sack plug (200') 8900' to 9100' Plug to be tagged.
5. Set 35 Sack plug (100') 7124' to 7224' Plug to be tagged.
6. Set 70 Sack plug (200') 1700' to 1900' Plug to be tagged.
7. Set 15 Sack plug (50') Surface to 50'.

18. I hereby certify that the foregoing is true and correct

SIGNED

Eddie J. Schuch

TITLE Operations Coordinator

DATE 4-28-89

(This space for Federal or State office use)

APPROVED BY

Shannon J. Shaw

TITLE

FOR: CHIEF, OPERATIONS

DATE

5-15-89

*See Instructions on Reverse Side