

- C. Any plastic material used to line pits must be removed to below ground level before pits are covered. If, upon abandonment of the wells, the retention of the well pad and/or access road is not considered necessary for the management and multiple use of the natural resources, they will be ripped a minimum of 12" in depth. All ripped surfaces are to be protected from vehicular travel by construction of a dead-end ditch and earthen barricade at the entrance to these ripped areas. (Reseeding of the affected areas may be required at the discretion of the BLM authorized officer).
- D. Within 15 days after plugging the well, a Subsequent Report of Abandonment is to be filed on Form 9-331 in quintuplicate showing the manner in which the well was plugged, including depths where casing was cut and pulled from, intervals, by depths, where cement plugs were placed, and the date plugging was completed. When all surface restoration work is completed, advise the District Office so that a field inspection of the wellsite can be made.