Form 3160-5 June (990)	UNITED STA DEPARTMENT OF TI BUREAU OF LAND M		FORM APPROVED FORM APPROVED Budget Bureau No. 1004- Expires: March 31, 199 .5. Lease Designation and Serial	3
		Artopia	NM 2834	NO.
Do not use this for	SUNDRY NOTICES AND RE		6. If Indian. Allottee or Tribe Na	ame
	e "APPLICATION FOR PERMI		ent leservoir.	
			7. If Unit or CA, Agreement De	SIRRation
	SUBMIT IN TRIF	LICATE		- Bungangan
I. Type of Well			SW-381	
Oil Gas Well X Well 2. Name of Operator	Other		8. Well Name and No.	
Fasken 0il & Ranc	b. Itd.		Shell Federal Com. #	<u>#5</u>
3. Address and Telephone No.			30-015-22900	
	e 1900, Midland, TX 79701	915-687-1777	10. Field and Pool, or Exploratory	/ Area
 Location of Weil (Footage, 1835' FNL & 1980' 	Sec., T., R., M., or Survey Description)		Cemetery (Morrow)	
Unit G, Sec. 5, 1			11. County or Parish, State	
	PROBRIATE ROXAL TO IN		Eddy, NM	
		DICATE NATURE OF NO	TICE, REPORT, OR OTHER DATA	
TYPE OF SU	BMISSION	TYPE OF ACTION		
Notice of Int	lent	Abandonment	Change of Plans	
X Subsequent 6		Recompletion		
A Subsequent	Report	Plugging Back	Non-Routine Fracturing	
X Subsequent F				
	Nament Notice	Casing Repair	Water Shut-Off	
	onment Notice	Casing Repair Altering Casing Other	Conversion to Injection	
Describe Proposed or Complet		Altering Casing Other S, and give pertinent dates, including estimates of the second s	Conversion to Injection Conversion to Injection Dispose Water (Note: Report results of multiple completion Completion or Recompletion Report and Completion Report and Completion or Recompletion Report and Completion Report and	
Final Abando Final Abando Describe Proposed or Completing give subsurface locations prrow perfs 9497-957 prk below performed RUPU. NU BOP. R RIW w/4½" CIBP an RIW w/4½" packer Release TOSSD. C RIW w/4½" Arrowse FL to 7500'. Perf Strawn 8641- Acidize w/375 gal	ted Operations (Clearly state all pertinent detail and measured and true vertical depths for al 3'-9619-79' 5-27-98 to 6-3-98 elease packer @ 9593'. POW. d set @ 9600'. w/TOSSD w/1.87" "F" profile irc well with 2% KCl packer	Altering Casing . Other	Conversion to Injection Conversion to Injection Conversion of Recompletion Recompletion Completion of Recompletion Recompletion Recompletion Recompletion Completion Recompletion Completion Conversion of Injection Conversion to Injection Conversio	a Log torm. naliy dril
Final Abando Final Abando Describe Proposed or Completing give subsurface locations prrow perfs 9497-957 prk below performed RUPU. NU BOP. R RIW w/4½" CIBP an RIW w/4½" packer Release TOSSD. C RIW w/4½" Arrowse FL to 7500'. Perf Strawn 8641- Acidize w/375 gal Flow back and tes	ted Operations (Clearly state all pertinent detail and measured and true vertical depths for all 3'-9619-79' 5-27-98 to 6-3-98 elease packer @ 9593'. POW. d set @ 9600'. w/TOSSD w/1.87" "F" profile irc well with 2% KCl packer t I 10k packer w/TOSSD w/1.7 56' w/2 JSPF w/1-11/16" stri s. 15% HCl + 375 gals. Methai t. 7-15-98 flow 54 mcfpd @ 30	Altering Casing Other s. and give pertinent dates, including estin markers and zones pertinent to this wor nipple with check valve. fluid. POW w/tbg. 81" "F" profile and 2-3/8" p gun. nol + CO ₂ . D psi TP. Majority of flo ACCEPTED FOR RE (ORIG. SGD.) DAY	Conversion to Injection Conversion to Injection Conversion of Recompletion Recompletion Completion of Recompletion Recompletion Recompletion Recompletion Completion Recompletion Completion Conversion of Injection Conversion to Injection Conversio	a Log torm. naliy dril
Final Abando Describe Proposed or Completing give subsurface locations prrow perfs 9497-957 prk below performed RUPU. NU BOP. R RIW w/4½" CIBP an RIW w/4½" CIBP an RIW w/4½" CIBP an RIW w/4½" Arrowse FL to 7500'. Perf Strawn 8641- Acidize w/375 gal Flow back and tes	ted Operations (Clearly state all pertinent detail and measured and true vertical depths for all 3'-9619-79' 5-27-98 to 6-3-98 elease packer @ 9593'. POW. d set @ 9600'. w/TOSSD w/1.87" "F" profile irc well with 2% KCl packer t I 10k packer w/TOSSD w/1.7 56' w/2 JSPF w/1-11/16" stri s. 15% HCl + 375 gals. Methai t. 7-15-98 flow 54 mcfpd @ 30	Altering Casing . Other	Conversion to Injection Conversion to Injection Completion or Recombined Report and mated date of starting any proposed work. If well is direction rk.)* Set packer @ 9454'. ' N-80 tbg. Set pkr. at 8604'. Swab ow still from Morrow. CORD VIDT. GLASS 98 8-19-98	a Log torm. naliy drill
Final Abando Final Abando Describe Proposed or Completing give subsurface locations prrow perfs 9497-957 prk below performed RUPU. NU BOP. R RIW w/4½" CIBP an RIW w/4½" CIBP an RIW w/4½" CIBP an RIW w/4½" Arrowse FL to 7500'. Perf Strawn 8641- Acidize w/375 gal Flow back and tes Flow back and tes	red Operations (Clearly state all pertinent detail and measured and true vertical depths for all 3'-9619-79' 5-27-98 to 6-3-98 elease packer @ 9593'. POW. d set @ 9600'. w/TOSSD w/1.87" "F" profile irc well with 2% KCl packer t I 10k packer w/TOSSD w/1.7 56' w/2 JSPF w/1-11/16" stri s. 15% HCl + 375 gals. Methai t. 7-15-98 flow 54 mcfpd @ 30 t. 7-15-98 flow 54 mcfpd @ 30	Altering Casing . Other	Conversion to Injection Conversion to Injection Completion of Recompletion Recompletion Recompletion Recompletion and Recompletion rk.)* Set packer @ 9454'. ' N-80 tbg. Set pkr. at 8604'. Swab ow still from Morrow. CORD VIDT. GLASS 93	a Log torm. naliy drill
Final Abando Describe Proposed or Completing ive subsurface locations prrow perfs 9497-957 prk below performed . RUPU. NU BOP. R . RIW w/4½" CIBP an . RIW w/4½" DIBP an . RIW w/4½" Arrowse . FL to 7500'. . Perf Strawn 8641- . Acidize w/375 gal . Flow back and tes . Flow back and tes . I hereby certify that the forego . Signed	red Operations (Clearly state all pertinent detail and measured and true vertical depths for all 3'-9619-79' 5-27-98 to 6-3-98 elease packer @ 9593'. POW. d set @ 9600'. w/TOSSD w/1.87" "F" profile irc well with 2% KCl packer t I 10k packer w/TOSSD w/1.7 56' w/2 JSPF w/1-11/16" stri s. 15% HCl + 375 gals. Methai t. 7-15-98 flow 54 mcfpd @ 30 t. 7-15-98 flow 54 mcfpd @ 30	Altering Casing . Other	Conversion to Injection Conversion to Injection Completion or Recombined Report and mated date of starting any proposed work. If well is direction rk.)* Set packer @ 9454'. ' N-80 tbg. Set pkr. at 8604'. Swab ow still from Morrow. CORD VIDT. GLASS 98 8-19-98	a Log torm. naliy drill
Final Abando Final Abando Describe Proposed or Completing give subsurface locations prrow perfs 9497-957 prk below performed RUPU. NU BOP. R RIW w/4½" CIBP an RIW w/4½" CIBP an RIW w/4½" Packer Release TOSSD. C RIW w/4½" Arrowse FL to 7500'. Perf Strawn 8641- Acidize w/375 gal Flow back and tes Flow back and tes I hereby certify that the forego. Signed	ied Operations (Clearly state all pertinent detail and measured and true vertical depths for all 3'-9619-79' 5-27-98 to 6-3-98 elease packer @ 9593'. POW. d set @ 9600'. w/TOSSD w/1.87" "F" profile irc well with 2% KCl packer t I lok packer w/TOSSD w/1.7 56' w/2 JSPF w/1-11/16" strips. s. 15% HCl + 375 gals. Methait. t. 7-15-98 flow 54 mcfpd @ 30 ing is true and correct ctm ctm coffice use)	Altering Casing . Other	Conversion to Injection Conversion to Injection Completion or Recombinion Report and mated date of starting any proposed work. If well is direction rk.)* Set packer @ 9454'. ' N-80 tbg. Set pkr. at 8604'. Swab ow still from Morrow. CORD VIDT. GLASS 98 Date	a Log torm. naliy drill

instruction on Reverse Side 266