

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S. mms	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED BY

JUL 1 1985

O. C. D.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease

State ☒ Fee ☐

5. State Oil & Gas Lease No.

V-171

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TXO Production Corp.	8. Farm or Lease Name Catclaw Draw St Com
3. Address of Operator 900 Wilco Bldg., Midland, TX 79701	9. Well No. 1
4. Location of Well UNIT LETTER M, 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 18 TOWNSHIP 21-S RANGE 26-E NMPM.	10. Field and Pool, or Wildcat Catclaw Draw (Strawn)
15. Elevation (Show whether DF, RT, GR, etc.) 3311 GR	11. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☒
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TOH w/2 3/8" tbg and uni-6 pkr.
TIH w/GR & junk basket to 9010'.
Free pt 4 1/2" csg (free pt app. 7300')
Set 4 1/2" CIBP @ 9000'. Dump 35' cmt.
* TIH & set 10" sx @ 8750-8650'.
* Set 10" sx @ 8000-7900'.
Cut & pull 4 1/2" @ 7300' (50' above free pt).
TIH & set 35 sx cmt @ 7350' (on 4 1/2" stab).
Tag TOC (app. 50' in OH).
Set 35 sx @ 5400' (in OH). & tag BASED ON F.P. 7/29/85 (50' in/out)
Set 35 sx @ 4200' (in OH)
Set 35 sx @ 2300' (at 8 5/8" shoe)
Tag TOC (app. 50' into 8 5/8").
Set 35 sx @ 550' (in 8 5/8").
Set 10 sx @ surface.

SHOULD
BE 2600
ASPER LB
SEE BACK
SHEET

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dale D. Lovely TITLE Production Engineer DATE 6-25-85

APPROVED BY M.A. Williams TITLE OIL AND GAS INSPECTOR DATE JUL 08 1985

CONDITIONS OF APPROVAL, IF ANY: * Minimum Plug 25 SX

Notify N.M.O.C.C. in sufficient time to witness