

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2688
Santa Fe, New Mexico 87504-2088

MAY 10 1991

O. C. D.

ARTESIA OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐

GAS WELL ☐

OTHER P&A

2. Name of Operator
YATES PETROLEUM CORPORATION (505) 748-1471

3. Address of Operator
105 South 4th St., Artesia, New Mexico 88210

4. Well Location
Unit Letter M : 660 Feet From The South Line and 660 Feet From The West Line

Section 18 Township 21S Range 26E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3311' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug well as follows:

- 1) Spot 25 sx Class "C" cement plug from 4000-3753' (cover perms 3883-3948')
- 2) Spot 25 sx Class "C" cement plug from 3200-2953' (cover perms 3122-3141')
- 3) Spot 25 sx Class "C" cement plug from 2700-2453' (cover perms 2654-61' and 8-5/8" casing shoe at 2552')
- 4) Perforate 5 1/2" casing at 550' with 4 SPF @ 90° phasing. After perforating, RIH with gun and tag plug at 2453'.
- 5) Pump approximately 150 sx Class "C" cement to fill the 5 1/2" casing and 8-5/8" x 5 1/2" annulus from 550' to surface with cement. Pump additional cement if necessary to circulate cement. (cover 11-3/4" casing shoe at 500' and surface plug).
- 6) Cut off wellhead and install regulation abandonment marker.

NOTE: NOTIFY NMOCD, ARTESIA, NM, 24 HRS BEFORE STARTING OPERATIONS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: Juanita Goodlett TITLE: Production Supervisor DATE: 5-9-91

TYPE OR PRINT NAME: Juanita Goodlett

TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

TITLE

DATE

MAY 10 1991

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness

Plugging