

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 9818

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

OXY USA Inc.

3. ADDRESS OF OPERATOR

P.O. Box 50250 - Midland, Texas 79710

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL & 1980' FEL

14. PERMIT NO.

30-015-22399

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3271' GR

7. AGREEMENT NAME

8. FARM OR LEASE NAME

Government S

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Winchester Morrow (Gas)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 3-T20S-R28E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) Abn. Lower Morrow & Test Upper Morrow

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

O.T.D. 11329' Shale, PBTD 11085'. The Lower Morrow Perfs were blanked off and the Upper Morrow Formation was tested in the following manner:

MIRU a completion unit and RU wireline and RIH and set a blanking plug in the F nipple @ 11116', blanking off the Lower Morrow Perfs @ 11214 - 11237. POOH w/WL. ND WH, NU BOP's and released the tubing from the Model DB packer set @ 11100' and POOH with the tubing. Perforated the Upper Morrow Formation w/2 SPF @ 10822, 23, 24, 27, 28, 10966, 97, 98, 11007, 08, 09, 13, 14, 15, 16, 46, 48, 49, 51, 52, and 11053'. Total 42 holes (0.43" dia & 14.70" pen in Berea). RIH w/5-1/2" Baker Loc-set packer w/on-off tool w/Model F profile nipple on 2-7/8" tubing and set the packer @ 10693'. 12 hr. SITP 0#. Released the packer but the packer would not go down the hole. POOH w/packer and tubing. Dumped 2 sacks of cement on top of the Model DB packer set @ 11100' for a PBTD of 11085'. RIH w/5-1/2" Baker Loc-set packer w/on-off tool and 1.87" Model F nipple on 2-7/8" tubing and set the packer @ 10673 and the tubing @ 10676'. 12 hr. SITP 0#. Swabbed -0- BO + 58 BLW/7 hrs. w/3 - 4' flare. Acidized thru Upper Morrow Perfs @ 10822 - 11053' w/3000 gals 7-1/2% NeFe HCl acid + 1000 SCF N₂/bbl. Total N₂=130,000 SCF. Max press 5900#, min press 2700#, ATP 4473#, AIR 5.7 BPM, ISIP 4300#, 5 min SIP 3990#, 10 min SIP 3850#, 15 min SIP 3800#. Flowed on 4 pt. test as follows: (Continued an attached sheet)

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Dist. Opr. Mgr. Prod.

DATE 11-28-88

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

DEC 28 1988

*See Instructions on Reverse Side

SJS
CARLSBAD, NEW MEXICO

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.