	UNITED STATES UNITED STATES SUBMIT IN TRIPLICATE* Other instructions on re- DEPARTMENT OF THE INTERIOR verse side)	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.	
	GEOLOGICAL SURVEY	NM 055756	2 RECEIVED
	CUNDRY MOTICES AND DEPONTS ON WELLS	6. IF INDIAN, ALLO	TTEE OR TRIBE NAME
	SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)		MAV 1 1 100
	Use "APPLICATION FOR PERMIT-" for such proposals.)		MAY 1 1 1981
1.	OIL GAS []	7. UNIT AGREEMENT	r name
	WELL WELL X OTHER		O. C. D.
2.	NAME OF OPERATOR		NAMERTESIA, OFFICE
	Southland Royalty Company /	Citgo Feder	al Com 3
3.	ADDRESS OF OPERATOR	!	
<i>-</i>	1100 Wall Towers West Midland, Texas 79701	10, FIELD AND POO	T OR WILLDOWN
	See also space 17 below.)	Und.	in the second second
	660' FENL & 1980' FEL	11. SEC., T., B., M.,	OR BLK. AND
	Yayar San	SURVEY OR A	REA
	PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, CR. gld.) NEXICO	Sec 5, T-20	-S R-28-F
14.	PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, OR, etc.)	12. COUNTY OR PAI	
	3328.6' GR	Eddy	New Mexico
	·	<u> </u>	1 New Mexico
Check Appropriate Box To Indicate Nature of Notice, Report, or Oth			•
	NOTICE OF INTENTION TO:		
	TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRI	NG WELL
	FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERIN	G CASING
	SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING	ABANDON	
	REPAIR WELL CHANGE PLANS (Other) PB & comple		
	(Other) (Note: Report results Completion or Recompl	etion Report and Log	g form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-			
	nent to this work.) *	a depens for all mar	ners and nones perci
	Perforate w/2 JSPF 11,060-11,070'. Had weak blow. swabbed gas. GIH w/cmt retainer & set 2 11,040'. Pmp 100 sxs Cl 7000#. Rev out 75 sxs. Spot 250 gals 7 1/2% acetic acid w 1 JSPF @ 10,808-16, 20-34, 38-56, 74-82, 10,894-10,905'. A 7 1/2% HCL acid & 169,000 SCF CO2. Testing Morrow perfs. w/cmt retainer & set @ 10,700'. Sting into retainer & sqz Cl "H" cmt to 3000#. Stung out of retainer & left 10' cmt 12 sxs. Spot 250 gals 10% acetic acid. Perf 1 JSPF from 10 w/2800 gals 7 1/2% MSR acid & 75,000 SCF N2. Swabbed dry. perfs. Rig up to frac Atoka. Frac w/15,000 gals Terra fr (33%) 36 tons liquid CO2, 8500# 100 mesh sd & 7850# 20-40 Testing 4/14/81. GIH w/CIBP & set @ 10,390'. Dump 35' of 250 gal 10% acetic acid. Perf 1 JSPF from 10,135-10,154'. perfs. Swab to test.	"H" & sqz pe /perf gun & cdz w/9000 g SI 1/24/81. perfs w/100 on top. Rev ,456-10,470' Testing Ato ac T40 + 750 sintered Bau cmt on plug.	rfs to perf als GIH sxs out Acdz ka 0 gal xite. Spot
-	I hereby certify that the foregoing is true and correct SIGNED		
	CONDITIONS OF APPROVAL, IF ANY:	DAIR	
	MAY 4 1981		
	*See Instructions on Reverse Side U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO		