

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		SEP 15 1980	
2. NAME OF OPERATOR Marathon Oil Company		O. C. D.	
3. ADDRESS OF OPERATOR P.O. Box 2409 Hobbs, NM 88240		ARTESIA, OFFICE	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 800' FNL & 200' FEL Sec. 30, T-21S, R-23E		5. LEASE DESIGNATION AND SERIAL NO. NM 0384625	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) RKB 4085', GL 4069'	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
NOTICE OF INTENTION TO:		7. UNIT AGREEMENT NAME Indian Basin	
TEST WATER SHUT-OFF <input type="checkbox"/>		8. FARM OR LEASE NAME Fed. IBD Gas Com	
FRACTURE TREAT <input type="checkbox"/>		9. WELL NO. 2	
SHOOT OR ACIDIZE <input type="checkbox"/>		10. FIELD AND POOL, OR WILDCAT Indian Basin - Upper Penn	
REPAIR WELL <input type="checkbox"/>		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 30, T-21S, R-23E	
(Other) <input type="checkbox"/>		12. COUNTY OR PARISH Eddy	
PULL OR ALTER CASING <input type="checkbox"/>		13. STATE NM	
MULTIPLE COMPLETE <input type="checkbox"/>			
ABANDON* <input type="checkbox"/>			
CHANGE PLANS <input type="checkbox"/>			
(Other) <input type="checkbox"/>			
WATER SHUT-OFF <input type="checkbox"/>		12. COUNTY OR PARISH Eddy	
FRACTURE TREATMENT <input type="checkbox"/>		13. STATE NM	
SHOOTING OR ACIDIZING <input checked="" type="checkbox"/>			
(Other) <input type="checkbox"/>			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

8-8-80 Spotted 100 gal. 10% M.S.A. acid over zone to be perforated. POOH w/tubing, perforated Upper Penn fr/7262 - 7278 (17 holes). RIH w/2 3/8" tubing and displaced perforating acid into formation, break down pressure 5000 psi. Pumped 2 BPM at 2800 psi.

8-9-80 Begin swabbing and testing.

RECEIVED

AUG 26 1980

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Ralph M. DePenaTITLE Production EngineerDATE 8-25-80

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

ACCEPTED FOR RECORD
DATE _____

AUG 28 1980

*See Instructions on Reverse Side

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO