BUREAL	JNI D STATES MEN. OF THE INTERIOR JOF LAND MANAGEMENT	SUBMIT IN TRIPI (Other Instruction verse side)		I SERIAL NO.	
on the form for propo	TICES AND REPORTS ON isals to drill or to deepen or plug back to ATION FOR PERMIT-" for such proposa	a different reservoir.	7. UNIT AGREEMENT NAME	MOC IV WIL	
OIL GAS OTHER		RECEIVED	7. UNIT AGHELMENT HAVING		
2 NAME OF OPERATOR OXY USA IN	ıc./	DEC 2 3 1991	8. FARM OR LEASE NAME GOVERNMENT A	λ N	
3. ADDRESS OF OPERATOR P.O. BOX 50250 MIDLAND, TX 79710		O. C. D.	9.WELLNO.	9. WELL NO. 1 10. DIELDAND PSÉL, OF WILD CAY / / //	
LOCATION OF WELL (Report location clearly an See also space 17 below.) At surface	d in accordance with any State requirements.*	1717 W 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	JUNDES BONE	HAINGS COM	
660 FNL 1980 FWL SEC 3 T20S R28E			SURMEY OR AREA		
	15. ELEVATIONS (Show wheter DF, RT, GR, etc.)		SEC 3 T20S R2 12 COUNTY OR PARISH	13. STATE	
14. PERMIT NO. 3001523562		3284	EDDY	NM	
16 Check Appro	opriate Box To Indicate Nature	of Notices, Report,	or Other Data BSEQUENTREPORTOF:		
TESTWATER SHUT-OFF PUI FRACTURE TREAT MU SHOOT OR ACIDIZE ABO	LLORALTER CASING LITPLE COMPLETE ANDON*	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other)	REPARING ALTERING (ABANDONIA	CASING X	
REPAIRWELL CH	ANGEPLANS	(Note: Report resu	Its of multiple completion on completion Report and Log for	Well rm.)	
need to this work)*	directionally diffied, give substitute 1992	nt details, and five pertinent tions and measured and true			
MIRU PU, NDWH, NUBOP, PO RIH W/ 5-1/2" CIBP & SET @ 3 POOH TO 475' & SPOT 10 sx		3350' 4386' - 4422' & SET @ 4350', DU UD-LADEN FLUID, SF CASING SHOE FR T OFF WH, INSTALL	MP 4sx (40') CEMENT POT 15sx (150') CEME OM 475' - 375'. POOH DRY HOLE MARKER.	ON TOP. INT ON TOP. ITO 63' &	
TD - 11275' PE MIRU PU, NDWH, NUBOP, PO RIH W/ 5-1/2" CIBP & SET @ 3 POOH TO 475' & SPOT 10 sx SPOT 15 sy CEMENT PLUG FE	OOH W/ TBG. RIH W/ 5-1/2" CIBI 100'. CIRC HOLE W/ 9.5ppg M CEMENT PLUG ACROSS 13-3/8 ROM 63'-SURFACE. POOH, CU	3350' 4386' - 4422' 2 & SET @ 4350', DU UD-LADEN FLUID, SF B CASING SHOE FROT T OFF WH, INSTALL DUNCAN WHITLOCK	MP 4sx (40') CEMENT POT 15sx (150') CEME OM 475' - 375'. POOH DRY HOLE MARKER. K - BLM	ON TOP. :NT ON TOP. 1 TO 63' &	
TD - 11275' PE MIRU PU, NDWH, NUBOP, PO RIH W/ 5-1/2" CIBP & SET @ 3 POOH TO 475' & SPOT 10 sx SPOT 15 sy CEMENT PLUG FE	Approved a line surrace reatorius in surrace reatorius in state and surrace reatorius in surr	3350' 4386' - 4422' 2 & SET @ 4350', DU UD-LADEN FLUID, SF B CASING SHOE FROT T OFF WH, INSTALL DUNCAN WHITLOCK	MP 4sx (40') CEMENT POT 15sx (150') CEME OM 475' - 375'. POOH DRY HOLE MARKER. K - BLM	ON TOP. INT ON TOP. I TO 63' & WELL FID-2 10-92 PH	

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fradulent statements or representations as to any matter within its jurisdiction.