Submit 3 Copies to Appropriate District Office

State of New Mexico

Form	C	-100	3
Revis	ed	1-1	-8

Ener

CONDITIONS OF APPROVAL, IF NYTY

nerals and Natural Resources Department

OII.	CONSERVATION	DIVISION
	COLIDER	

DISTRICTI	OIL CONSERVAT	TON DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	PO Box	2088	30-015-23610
DICT II	Santa Fe, New Mexi	87504-2088 RECEIVED	5. Indicate Type of Lease STATE FEE X
P.O. Drawer DD, Artesia, NM 88210			6. State Oil & Gas Lease No.
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		NOV - 6 1991	
		MELLS	
(DO NOT USE THIS FORM FOR PE	TICES AND REPORTS ON V ROPOSALS TO DRILL OR TO DEE ERVOIR. USE "APPLICATION FOR C-101) FOR SUCH PROPOSALS.)	PEANTESIA ()PICE	7. Lease Name or Unit Agreement Name
1. Type of Well:			North Carlsbad OK Com
OIL GAS WELL X	C OTHER REC	COMPLETION	8. Weil No.
2. Name of Operator			1
YATES PETROLEUM CORPO	ORATION V		9. Pool name or Wildcat
3. Address of Operator	rtesia. NM 88210		Undes. Atoka
105 South 4th St., An			East Line
4. Well Location B 6	60 Feet From The North	Line and165	50 Feet From The East Line
Unit Letter::			Edder County
Section 26	Township 21S	Range 26E	NMPM Eddy
	11/1//////////////////////////////////	heiher DF, RKB, RT, GR, etc.) 31' GR	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
X/////////////////////////////////////	(//////) 31	JI GR	Report, or Other Data
11. Chec	k Appropriate Box to Indic	cate Nature of Notice, I	BSEQUENT REPORT OF:
NOTICE OF I	NTENTION TO:	50	DOE GOE AT THE T
		REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	COMMENCE DRILLIN	NG OPNS. PLUG AND ABANDONMENT
<u>-</u>	OUTS OF DIAME	I I COMMENCE DEILLI	
TEMPORARILY ABANDON L	CHANGE PLANS	<u> </u>	
TEMPORARILY ABANDON	CHANGE PLANS	CASING TEST AND	CEMENT JOB
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND	CEMENT JOB
PULL OR ALTER CASING		CASING TEST AND OTHER: Plugbac	CEMENT JOB
OTHER: 12. Describe Proposed or Completed Country SEE RULE 1103.	Operations (Clearly state all pertinent de	CASING TEST AND OTHER: Plugbac	CEMENT JOB k, perforate & treat Atoka X Zone. Cluding estimated date of starting any proposed
PULL OR ALTER CASING OTHER: 12 Describe Proposed or Completed Co	Operations (Clearly state all pertinent de	CASING TEST AND OTHER: Plugbace partials, and give pertinent dates, incodes as follows: -10696' (6 holes-1	CEMENT JOB Ek, perforate & treat Atoka Zone. Cluding estimated date of starting any proposed 10666-10670' and 10673-10677' 1 SPF). Acidized perforations