

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYForm approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER	2. NAME OF OPERATOR Perry R. Bass	3. ADDRESS OF OPERATOR Box 2760, Midland, TX 79707	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FWL & 660 FSL OF SECTION - UNIT PLATTER N.	5. LEASE DESIGNATION AND SERIAL NO. N.M. 02946	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	7. UNIT AGREEMENT NAME BIG EDDY UNIT	8. FARM OR LEASE NAME BIG EDDY UNIT	9. WELL NO. 85	10. FIELD AND POOL, OR WILDCAT GOLDEN LANE MORROW	11. SEC., T., R., M., OR B.R. AND SURVEY OR AREA SEC. 8, T. 21S, R. 29E	12. COUNTY OR PARISH EDDY	13. STATE N. Mex.
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RC, GR, etc.) 3366' GL											

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) 8 5/8" CASING

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

DRILLED 11" HOLE TO 3300'. RAN 10 JTS 8 5/8", 32#, K-55, STVC AND 65 JTS 8 5/8", 28", N-80, STVC CASING. SET ON BOTTOM @ 3300'. CEMENTED WITH 1400 SLS "LITE" PLUS ADDITIVES - TAILED WITH 250 SLS CLASS "C" PLUS ADDITIVES. BUMPED PLUG TO 2000#. PLUG DOWN @ 5:30 PM, MST, 6-4-81. FLOATS HELD - CIRC OUT 430 SLS. USGS WITNESS: JOHN WADE-ARTESIA. WOC. 21 HOURS. TESTED BOPE TO 5000# - HYDRILL TO 1500#. TAGGED CEMENT @ 3203' - DRILLED CEMENT, FLOAT AND SHOE. COMMENCED DRILLING 7 7/8" HOLE.

18. I hereby certify that the foregoing is true and correct

SIGNED

H. B. Murty, Jr.

TITLE

Sr. Prod. Clerk

DATE

June 15, 1981

(This space for Federal or State Use)

ACCEPTED FOR RECORD

PETER W. CHESTER

APPROVED BY

CONDITIONS OF APPROVAL, IF

TITLE

DATE

JUN 23 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.