

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

JUL 23 1992

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS O. C. D.

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☒ Other

RECOMPLETION

2. Name of Operator

YATES PETROLEUM CORPORATION

(505) 748-1471

3. Address and Telephone No.

105 South 4th St., Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit C, 600 FNL & 1750' FWL, Sec. 18-T21S-R22E

5. Lease Designation and Serial No.

NM 14459

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Mescal SE Federal #1

9. API Well No.

30-015-24002

10. Field and Pool, or Exploratory Area

Undes. Canyon

11. County or Parish, State

Eddy, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☒ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☒ Other Perforate, Treat  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

7-8-92. RUPU. TOH with packer and RBP. Bled down in 5 min. Bled off annulus and rig up Western. Load annulus w/1-1/2 bbls 2% KCL water. Unset packer at 7935'. TOH w/2-7/8" tubing and packer. TIH w/retrieving tool and 2-7/8" tubing to RBP at 8070'. Unset RBP. TOH w/tubing and RBP. TIH w/CIBP and set CIBP at 7930' with 35' of cement on top. Perforated 5872-6030' w/58 - .42" holes (2 SPF) as follows: 6024-30' (14 holes) 5996-6006' (22 holes) and 5872-82' (22 holes). TOH w/casing guns. TIH w/RBP, packer and 2-7/8" tubing. Set RBP at 6080' and packer set 5963'. Acidize perfs 5996-6030' w/4000 gals 15% NEFE and 48 balls. Reset RBP 5963', set packer at 5837'. Acidize perfs 5872-82' w/3000g. 15% NEFE acid and 32 balls. Unset packer. Drop down and unset RBP. Reset RBP at 6080', test to 2000 psi. Pull up and set packer at 5837'. Swabbed well.

JUL 7 1992  
SJS

14. I hereby certify that the foregoing is true and correct

Signed [Signature]

Title Production Supervisor

Date 7-15-92

(This space for Federal or State office use)

Approved by \_\_\_\_\_  
Conditions of approval, if any:

Title \_\_\_\_\_

Date \_\_\_\_\_

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side