

UNIT STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Form approved  
Budget Bureau No. 1004--0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-01165

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Yates Federal

9. WELL NO.

#5

10. FIELD AND POOL OR WILDCAT

Burton Flat, East (Wolfcamp)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 17. T-20-S, R-29-E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

TXO Production Corp.

3. ADDRESS OF OPERATOR

415 West Wall, Suite 900, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface

990' FSL & 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3290 GL, 3306 KB

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 5-22-90 MIRU WO unit. TOH w/2 3/8" tbg & pkr. (300 jts). Set CIBP @ 9440'. Dump 50' cmt on top of plg. ND WH. RU & remove csg slips. Install BOP.
- 5-23-90 Load hole w/50 bbls 2% KCL. Rec 98 jts 4 1/2", 11.6#, K-55, LT&C (4078.75') & 20.74' cutoff. RU HLS, log open hole w/CNL, FDC, DLL. Verbal approval rec'd to pmp 300' cmt plg @ 5800' fr Tom Hare, BLM per telephone conversation w/TXO on 5/23/90. Approval was rec'd to spot a plg 100' in the 4 1/2" csg stub w/o tagging the 1st plg.
- 5-24-90 TIH w/tbg to 4100'. Enter csg stub. Mix & pmp 25 sx "C" @ 5850'. TOH to 4220'. Mix and pmp 75 sx "C" w/2% CaCl @ 4220'. POH w/8 stds tbg. Rev w/75 bbls frsh wtr. TOH.
- 5-25-90 TIH w/2 7/8" tbg. Tag cmt plg @ 4007'. BLM witnessed tag. TOH w/tbg. TIH w/SN, 95 jts tbg to 2995', ND BOP. NU WH. RU swb. Swb 7 1/2 hrs.
- 5-26-90 RD PU & SI for evaluation.
- thru
- 5-29-90

ACCEPTED FOR RECORD

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Drilling Secretary

DATE June 1, 1990

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side