

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NEW OIL CONVEYANCE COMMISSION
SUBMIT IN TRIPI
(Other instructions
verse side)
Artesia, NM 88210

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO
NM-01119

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Yates C Federal

9. WELL NO.

35

10. FIELD AND POOL OF WELL

Undesig. Avalon

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 5, T21S, R27E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry

2. NAME OF OPERATOR

Exxon Corporation

3. ADDRESS OF OPERATOR

P. O. Box 1600, Midland, TX 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

563' FNL & 560' FEL

RECEIVED BY

JUN 11 1986

O.C.D.
ARTESIA, OFFICE

14. PERMIT NO

30-015-24696

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

KB-3220

GR-3208

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

XX

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The above well was plugged and abandoned in the following manner:

Set plug 2600-2407 w/20 sx C1C.
Set plug 698-507 w/20 sx C1C.
Set plug 411-surface w/45 sx C1C.

Cut off wellhead and installed dry hole marker.

P & A 10-30-85.

18. I hereby certify that the foregoing is true and correct

SIGNED

Melva Knippling

TITLE

Unit Head

DATE

11-25-85

(This space for Federal or State office use)
Orig. Sgd. Charles S. Dench

APPROVED BY

Area Manager

TITLE

DATE

6-10-86

CONDITIONS OF APPROVAL, IF ANY:

Post ID-2
12-6-85
P & A

*See Instructions on Reverse Side