Formerly 9–331) DEPARTN BUREAL	OF LAND MANAGE	TS ON WELLS	E• r <del>t</del>	Form approved. Budget Bureau Expires August 5. LEASE DESIGNATION NM-01119 6. IF INDIAN, ALLOTTE	No. 1004-0135 31, 1985 AND BERIAL NO.
(Do not use this form for propos Use "APPLICA 		plug back to a different reservoir. auch proposals.)		7. UNIT AGREEMENT N	AME
2. HANE OF OPERATOR Exxon Corporat				8. FARM ON LEASE WA Yates C Fede	
S. ADDRESS OF OFEATOR P. O. Box 1600	, Midland, TX	9702 RECEIVED BY		9. WELL NO. 35	
<ol> <li>LOCATION OF WELL (Report location of See also space 17 below.) At surface</li> </ol>		JUN 17 1980		10. FIELD AND POOL, ( Undesig. Ava 11. EBC., T., B., M., OR SURVEY OR ABS	alon - Laci
563' FNL & 560' 1		O. C. D. ARTESIA, OFFICE		Sec. 5, T21	
14. PERNIT NO. 30-015-24696	15. BLEVATIONS (Show when KB-3220			12. COUPTY ON PARIS Eddy	E 13. STATE NM
16. Check Ap		ate Nature of Notice, Report		Other Data	
TEST WATER SEUT-OFF FRACTURE TREAT SROOT OB ACIDIZE REPAIR WELL (Other)	PULL OR ALTER CABING MULTIPLE COMPLETE ABANDON <sup>®</sup> CHANGE PLANE tion Release X	Completion or I	results tecompl	of multiple completion letion Report and Log f	CABING
ment to this work.) *	mally drilled, give subsuria	ertinent details, and give pertinent ce locations and measured and true			ite of starting an rs and sones perti

The location has been cleaned up and reseeded. The site is ready for inspection so that Exxon may be released from the location.

rreby writing that the foregoing is true and correct MED MILLA Engling TITLE	Section Head	6-16-86
	f re	out liney

\*See Instructions on Reverse Side