


EXXON COMPANY, U.S.A.

POST OFFICE BOX 10488 • MIDLAND, TEXAS 79702

MIDCONTINENT PRODUCTION DIVISION
SOUTHERN DRILLING ORGANIZATION

E W. THOMAS, Manager

W. F. BURCHARD, Operations Superintendent
K. S. ROSE, Operations Superintendent
M. C. WELBORN, Operations Superintendent
J. D. HOWELL, Engineering Manager

JUNE 13, 1984

LISTED BELOW ARE THE DEVIATION TESTS TAKEN ON BURTON FLAT FEDERAL "B"
NO. 3:

<u>DEPTH</u>	<u>DEGREES OF DEVIATION</u>	<u>DEPTH</u>	<u>DEGREES OF DEVIATION</u>
310	1/4	2165	1 1/2
600	3/4	2290	1 1/2
784	1	2483	1 1/2
838	1 1/2	2555	3/4
1004	1 3/4	2740	3/4
1098	1 1/2	3045	1/2
1193	2	3235	1/2
1252	1 3/4	3422	3/4
1315	2	3510	1/2
1377	2	3744	3/4
1438	2	3900	3/4
1531	2	4004	1/2
1615	1 3/4	4256	3/4
1739	1 3/4	4492	3/4
1829	2 1/2	4741	3/4
1894	2	4987	1
1990	1 1/2	5265	3/4
2010	1 1/2	5600	1/4

BY P. K. MendenhallSWORN TO and subscribed before me this 13th day of June, 1984Linda S. Jones
Notary Public
Midland, TexasMy commission expires: November 1985