

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Hondo Oil & Gas Company

3. Address and Telephone No.

P. O. Box 2208, Roswell, NM 88202 (505)625-6732

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

3009' FNL & 660' FWL; Sec.6-T21S-R27E

5. Lease Designation and Serial No.

NMNM-0501759

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Kurland "A" Fed. #1

9. API Well No.

300152484700S1

10. Field and Pool, or Exploratory Area

Avalon Delaware

11. County or Parish, State

Eddy Co., NM

2. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD @ 5077'

13 3/8" csg set @ 490' w/ TOC @ surface.

8 5/8" csg set @ 2305' w/ TOC @ surface.

5 1/2" csg set @ 5077' w/ TOC @ 2200'

PBTD @ 2685'. Perfs 2652'-2666'.

Note: Notify BLM 24 hrs prior to commencing P&A.

P&A per the following procedure (Approved by Shannon Shaw on 2/5/92):

- (1.) Set CIBP @ 2600' w/ 35' cmt on top.
- (2.) Cut & pull \pm 2000' of 5 1/2" csg.
- (3.) Spot 150' cmt plug across 5 1/2" stub @ 2000'. Tag plug.
- (4.) Spot 100' cmt plug from 540'-440'.
- (5.) Spot 50' cmt plug @ surface.
- (6.) Install dryhole marker.

Estimated date of starting the proposed work is 3/2/92.

14. I hereby certify that the foregoing is true and correct

Signed E. J. R. [Signature]

Title Petroleum Engineer

Date 02/06/92

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____

Date 2/11/92

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

***See Instruction on Reverse Side**