

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> Drilling well		5. LEASE DESIGNATION AND SERIAL NO. NM-17103	
2. NAME OF OPERATOR Liberty Oil & Gas Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 1776 Woodstead Court, Suite 200, The Woodlands, Texas 77380		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2100' FSL & 660' FWL		8. FARM OR LEASE NAME Lee Federal	
14. PERMIT NO.		9. WELL NO. 4	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3266.1' GR		10. FIELD AND POOL, OR WILDCAT Wildcat-Bone Spring	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 25, T20S, R28E	
		12. COUNTY OR PARISH Eddy	
		13. STATE N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5/22/84 Lost all circulation @ 1946'. Dry drilled to 2168'.
5/23/84 Drilled to 2198'. Drill string became stuck. Worked stuck pipe for 5 hours with no success. R.U. Ryco wireline and ran free point indicator. Found pipe to be free @ 1565'. Came out of hole with 1565' drill pipe, left 11" bit, shock sub, 3-8" drill collars, x-over sub, stabilizer and 17-6 1/4" drill collars in the hole (619' of fish). Made several attempts to recover fish, but failed. Received verbal approval to plug and abandon well from Armando Lopez 5/29/84.
Set balanced plug from 455'-355' with 75 sx of Class 'C' cement. Set 2nd plug from 15' to surface with 15 sx Class 'C' cement. Install dry hole marker. Rip reserve pits to let them dry to level. P & A complete 5/29/84.

I hereby certify that the foregoing is true and correct

SIGNED Jerry W. Franklin

TITLE Agent

DATE 7/03/84

(This space for Federal or State office use)

APPROVED BY
CONDITIONS

TITLE

DATE

ACCEPTED FOR RECORD

*See Instructions on Reverse Side

MAY 30 1986