

Florida Exploration - Eddy Co., N.M.

11/2/84 p.3

Wellsite drilling engineers were Frank Bronson of Midland and John Swindle, Consultant of Odessa, Texas.

The drilling contractor was Exeter Drilling Co. of Denver, Colorado - Rig 65. The rig was clean and well-kept. The drilling crews finished the hole despite numerous difficulties including crooked hole and lost circulation problems that were beyond the control of the contractor.

Since running electric logs at total depth, Dave Miller told me that casing has been set on the well for completion. I believe that is a correct decision.

Working with the various people on this well was a pleasure and a privilege. Please feel free to call on us at any time regarding this well or other areas where our expertise may be beneficial.

Very truly yours, Barney C. McCasland. James F. Trice

P.S. Our original sample-drill time log is enclosed.

BCM

Pr

RECEIVED

JAN 14 1985

O.C.D. HODBS O**ffice**