

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 0424859

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ API No. 30-015-25007

2. NAME OF OPERATOR

Oryx Energy Company

3. ADDRESS OF OPERATOR

P. O. Box 1861, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

P, 1200' FSL & 330' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4075.5' GR

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Bunnell Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Indian Basin Upper-Penn Gas

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

18-, T-21-S, R-23-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Correct Lease name spelling

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Correct lease name spelling from: Bunnell Federal To: Bunnell Federal

Post ID-3
8-10-90
correct lease name
spelling

18. I hereby certify that the foregoing is true and correct

SIGNED

Maria L. Perez

TITLE Proration Analyst

DATE 8-1-90

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 0424859

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ API No. 30-015-25007

2. NAME OF OPERATOR

Oryx Energy Company

3. ADDRESS OF OPERATOR

P. O. Box 1861, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

P, 1200' FSL & 330' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4075.5' GR

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Bunnel Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Indian Basin Upper-Penn Gas

11. SEC., T., R., E., or BLK. AND
SURVEY OR AREA

18, T-21-S, R-23-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANE

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. KILL WELL W/2% KCL WTR.
2. MIRU APPOLLO WL. RUN & SET "EL" PLUG IN PROFILE NIPPLE @ 6971. TEST TBG W/WTR TO 3,000 PSI. FISH PLUG.
3. APOLLO PERF (UPPER PENN) 7005-10, 7085-90, 7172-76 & 7209-18 W/2 JSPF 54 TOTAL HOLES W/1 11/16" THRU TBG DEEP JET GUN, .31" EH, 14 GC. AS PER SCHLM CN-LD LOG, DATED 10/10/84. POH W/GUN.
4. RIG UP BJ-TITAN. TRAP 500 PSI ON ANNULUS. BJ-TITAL ACDZ PERS 7005-7287 W/12,000 GALS 75 QUALITY 20% FEHCL IN 3 EQUAL STAGES W/500# GRS IN 250 GALS GELLED 10 PPG BRINE. ADJUST 2ND BLOCK AS NECESSARY. OVERFLUSH W/75 QUALITY 2% KCL WTR. PUMP @ 2 BPM. MWHPT - 3,000 PSI.
5. FLOW & SWAB BACK LOAD & ACID WTR. ONCE ABLE TO KICK WELL OFF, PUT THRU PRODUCTION UNIT TO TEST.

18. I hereby certify that the foregoing is true and correct

SIGNED

Maria L. Perez

TITLE

Proration Analyst

DATE

4-25-90

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side