

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

RECEIVED BY
MAY 12 1986

O. C. D.

P.O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fed <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDARY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO RE-LEASE OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Ray Westall	8. Farm or Lease Name Easeball Park
3. Address of Operator P.O. Box 4 Loco Hills, New Mexico 88255	9. Well No. 4
4. Location of Well UNIT LETTER H 2310 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 24 TOWNSHIP 22S RANGE 26E NMPM.	10. Field and Pool, or Wildcat Und. S. Carlsbad Delaware
15. Elevation (Show whether DF, RT, GR, etc.) 3150. GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER Spud, 8 5/8", T.D., 52 1/2"	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-25-86 Spud 12 3/4" hole @ 4:15 P.M.

4-26-86 Ran 14 jts. 422.31' of 8 5/8" 24# J-55 casing. Cemented @ 434' w/250 sxs Class "C" 2% CaCl. Circulated 25 sxs cement. Plug down @ 5:15 A.M. WOC 18 hrs. Pressured up 800# for 30 min. Held.

5-04-86 T.D. 4600'.

5-05-86 Ran 111 jts. 5 1/2" 17# J-55 casing, 4622.77'. Set & cemented @ 4600' w/350 sxs Nal. Lite 1/4# Floseal, 300 sxs 50/50 Poz "C" 6# salt, 1/4# Floseal, 3/10% Nalad 4, 750 gal. Flocheck 21. Plug down @ 4:00 P.M. 5-5-86.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ray Westall TITLE Operator DATE 5-9-86

Original Signed By
Mike Williams

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

Oil & Gas Inspector

DATE MAY 22 1986