Southern L Business Unit Domestic Production



P.O. Box 552 Midland, TX 79702-0552 Telephone 915/682-1626

June 1, 2001

Bureau of Land Management Attn: Mr. Gary Gourley 2909 West Second Street Roswell, New Mexico 88201

Dear Mr. Gourley,

It has come to my attention that I have filed completion forms for a well that had been recompleted in the Atoka formation as being in the Indian Basin Morrow Gas Pool. I was under the impression that the Atoka formation in the Indian Basin area was a part of the Morrow reservoir. I called Tim Gum, District Manager of the Oil Conservation Division in Artesia to confirm this, and He told me that the Atoka is not a part of the Morrow reservoir, and that I needed to send in corrected completion forms. Attached you will find the corrected completion form, 3160-4, for the Indian Hills Unit Well No. 6 Atoka completion along with the corrected sundry notice and a copy of the sundry notice that was originally sent in.

Please let me know if I need to turn in any other forms to get your records on this well corrected. Thank you for your help and understanding in this matter.

Sincerely,

Ginny Larke

Ginny Larke Engineer Technician

Attachments

