

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Artesia, NM 88210

SUBMIT IN
(Other Instru
verse side)

LOCATE
R OR RE

Budget Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL
NM-58511

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Indian Basin

9. WELL NO.

1

10. FIELD AND FOOT OR WILDCAT

Indian Basin Upper Penn

11. SEC., T., R., W., OR BLK. AND
SURVEY OR AREA

Sec. 8 T21S, R23E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL
WELL ☐ GAS
WELL ☒ OTHER

2. NAME OF OPERATOR

Santa Fe Exploration Company

3. ADDRESS OF OPERATOR

P. O. Box 1136, Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

660' FSL & 660' FEL Section 8, T21S, R23E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3987.8 GR

RECEIVED

JUL 26 '89

O. C. D.
ARTESIA, OFFICE

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRAC TREAT

SHOOT OR ACIDIZE

CEASE WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRAC TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DISCUSS PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti
nent to this work.)*

4 Jul 89 Called Carlsbad engineer Shannon Shaw & received plugging instructions.

5 Jul 89 Called to give Plugging Notice 10:00 A. M., commence pumping first plug
at 6:45 P. M.

Plugs	8790-8990	200'	1 Tag Plug	Morrow
	8230-8330	100'	2 No Tag	Strawn
	5930-6030	100'	3 No Tag	Wolfcamp
	4880-4980	100'	4 No Tag	Bone Springs
1575-1775 - 9 5/8 Csg shoe		200'	5 Tag Plug	Csg Shoe
	177-277	100'	6 No Tag	13 3/8 Csg Shoe
	0-50	50'	7 No Tag	Surface Plug

Jim Amos witnessed plugging of well.

18. I hereby certify that the foregoing is true and correct

SIGNED *Andrew Bertridg*

TITLE Petroleum Engineer

DATE 6 Jul 89

(This space for Federal or State office use)

APPROVED BY *Shannon Shaw*

FOR TITLE

DATE 7-24-89

CONDITIONS OF APPROVAL, IF ANY:

surface restoration is completed.

*See Instructions on Reverse Side