

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-53218
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Steve Sell

3. ADDRESS OF OPERATOR

P. O. Box 5061, Midland, Tx 79704

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit L, 1327' FSL, 1143' FWL, Sec 35, T21S, R24E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3857 KB

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Shafer Fed Comm

9. WELL NO.

1 - Reentry

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR R.R. AND SURVEY OR AREA

Sec 35, T21S, R24E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) TD Well, Log, T/A

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

12-23-89 TD 7 7/8" Hole @ 8270'. TOOH for Multishot.

12-24-89 TIH for Multishot (See Attached for Results).

12-25-89 Shut Down for Christmas.

12-26-89 TOOH for Logs. Logging. TIH to set plugs as follows:

- #1 Spotted 40 sx plug - 8270' - 8170' = Cisco
- #2 Spotted 40 sx plug - 7274' - 7174' = Wolfcamp
- #3 Spotted 90 sx plug - 5150' - 5000' = Bone Springs
- #4 Spotted 40 sx plug - 4520' - 4420' = Bone Springs
- #5 Spotted 40 sx plug - 3839' - 3739' = KOP
- #6 Spotted 90 sx plug - 2670' - 2400' = 9 5/8" Casing
- #7 Spotted 40 sx plug - 417' - 317' = 13 3/8" Casing
- #8 Spotted 10 sx plug - Surface

P.S. P&A PROCEDURE HAS BEEN APPROVED BY MR. MIKE WILLIAMS W/NMOCD.

18. I hereby certify that the foregoing is true and correct

SIGNED

John Pool

TITLE

Agent

DATE

12-28-89

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

1-11-90

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side