

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

(Other instructions on reverse side)

Expires August 31, 1985

3. LEASE DESIGNATION AND SERIAL

NM 58799

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Apache Federal

9. WELL NO.

10. FIELD AND POOL OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA

Sec. 21: T22S, R25E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Siete Oil and Gas Corporation

3. ADDRESS OF OPERATOR

P.O. Box 2523

Roswell, NM 88202-2523

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

1980' FSL & 2310' FEL, NW 1/4 SE 1/4, Unit Letter J

14. PERMIT NO

30-015-26163

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3629' GR

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANT

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Spud, Csg & 1"

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PAGE 2

9/05/89 3 bbls 60% Sodium Silicate & 50 sxs Class "C" w/5% CaCl, tagged 420', PD @ 10:15 PM.

9/06/89 Set plug @ 420' w/100 sxs 35/65 POZ w/6% D-20, 3% CaCl & 1/4# D-29, PD @ 12:30 AM, circ to surface, WOC, NU BOP & test to 1000# for 30 min, held ok, resumed drlg.

9/10/89 TD 7 7/8" hole to 4470' @ 6:00 PM, TOH, RU Schlumberger & ran DLL/MSFL & CNL/LDT on interval 1718'-4466', logger's TD @ 4468', SION.

9/11/89 TOH & lay dn 23 DC, TIH open-ended, PU 23 jts DP, circ hole, plug as abandoned as follows, set plug @ 4470'-4320' w/50 sxs class "A" Neat, lay dn 52 jts DP, set plug @ 2870'-2720' w/50 sxs class "A" Neat, lay dn 31 jts DP, set plug @ 1895' w/70 sxs class "A" w/4% CaCl, WOC 1 1/2 hrs, tagged cmt @ 1667', nipple dn, set plug @ 450'-350' w/30 sxs class "A" Neat, set plug @ 50'-surface w/16 sxs class "A" Neat, erect dry hole marker, released L&M Rig #1 @ 11:30 PM.

18. I hereby certify that the foregoing is true and correct

SIGNED

Cathy Bailey

TITLE

Drig. & Prod. Tech.

DATE

11/10/89

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side