

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

12 1992

O.C.D.

WELL API NO.

30-015-26280

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Lone Tree Federal Com.

8. Well No.

1

9. Pool name or Wildcat

East Carlsbad Morrow

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:

OIL
WELL ☐

OAS
WELL ☒

OTHER

2. Name of Operator

Collins & Ware, Inc

3. Address of Operator

303 W. Wall, Suite 2200, Midland, TX 79701

4. Well Location

Unit Letter N : 660 Feet From The South Line and 2120 Feet From The West Line

Section

24

Township

21-S

Range

27-E

NMIM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3126.4 GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☒

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP at 9675' and cap with 35' cement.
2. Set 25 sx plug at 9065'. *
3. Cut 5-1/2' casing at approximately 8150' and pull.
4. Set 25 sx plug at 8200' - 50' in/50' out - tag plug.
5. 35 sx plug at 5430'.
6. 35 sx plug at 2650'. *
7. 35 sx plug at 2300 - (tag plug).
8. 35 sx plug at 700'.
9. 10 sx plug at surface - weld plate and install marker.
10. Mud between all plugs.

Notify N.M.D. sufficient time to witness

Plugging

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

Agent for Collins & Ware

12-17-92

TYPE OR PRINT NAME

J. E. BRUSEN HAN

TELEPHONE NO. 915-683-5571

(This space for State Use)

* Plug 8930-9030
Plug 2445-2545

APPROVED BY

TITLE

2-22-93

DATE

1/1/93

CONDITIONS OF APPROVAL, IF ANY: