

Form 3160-5  
(July 1989)  
(Formerly 9-331)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING  
OFFICE FOR NUMBER  
OF COPIES REQUIRED  
(Other instructions on reverse side)

BLM Roswell District  
Modified Form No.  
ND60-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS OCT 19 '90

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		O. C. D. ARTESIA OFFICE	
2. NAME OF OPERATOR The Petroleum Corporation of Delaware		3a. Area Code & Phone No. 214-528-5898	
3. ADDRESS OF OPERATOR 3131 Turtle Creek Blvd., Ste. 400, Dallas, TX 75219-5415			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2130 FWL & 990 FSL			
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) Ground 3298 ft.	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		17. UNIT AGREEMENT NAME	
18. FARM OR LEASE NAME Superior Federal		19. WELL NO. 8	
20. FIELD AND POOL, OR WILDCAT East Burton Flat strawH		21. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 1, T20S, R29E	
22. COUNTY OR PARISH Eddy		23. STATE NM	

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	<input type="checkbox"/>	FULL OR ALTER CASING	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANE	<input type="checkbox"/>	(Other) Testing & Plug back	<input checked="" type="checkbox"/>		
(Other)							
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)							
17. DESCRIBE PROMISED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*							

Tested the Morrow through perforations at 11700-11708', zone swabbed dry. Too tight to produce. Set bridge plug at 11690 ft. and capped with cement P.B.D. 11670 ft.

Tested the Atoka through perforations at 11180-11186 ft. Well flowed dry gas burning with 12-14 ft. flare. Set bridge plug at 11070 and capped with cement. P.B.D. 11050 ft. completed well in the Strawn through perforations at 10755-10770, 10626-10638 and 10612-10622 ft.

\* UNECONOMICAL.

RECEIVED  
OCT 15 10 29 AM '90  
CARL AREA HEADQUARTERS  
OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE District Operations Engineer DATE 10-08-90

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE