

SUNDY NOTICES AND REPORTS ON WELLS

See back of this form for instructions to fill in. To prepare or give back to a District Supervisor. APPLICATION FOR PERMIT - (See back page) RECEIVED

NM-82853

451

DATE ☐ TIME ☐ OTHER ☐		MAR 11 1991	
NAME OF OPERATOR		O. C. D. ARTESIA OFFICE	
Siete Oil and Gas Corporation			
ADDRESS OF OPERATOR			
P.O. Box 2523, Roswell, NM 88202-2523			
LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 33 below.)		1. NAME OF LEASE NAME	
2460' FNL & 330' FWL, SW $\frac{1}{4}$ NW $\frac{1}{4}$, Unit Letter D		Blackfoot Federal	
		2. WELL NO.	
		1	
		3. FORM AND FOOT. ON WILDCAT	
		Wildcat	
		4. SEC. T. R. IN. ON MAP AND QUAD ON AREA	
		Sec. 17, T22S, R25E	
5. COUNTY OR PARISH		6. STATE	
Eddy		NM	
7. ELEVATION (Show whether top of hole or csg.)			
3828' GR			

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

COMPLETION REPORT ON:

WATER SHUT-OFF	☐	WELL OR ALTER CASING	☐	WATER SHUT-OFF	☐	STABILIZE WELL	☐
FRACURE TREAT	☐	MULTIPLE COMPLETS	☐	FRACURE TREATMENT	☐	ALTERING CASING	☐
SHUT IN ACTING	☐	ABANDON*	☐	SHUTTING ON ACTING	☒	ABANDONMENT*	☐
REPAIR WELL	☐	CHANGE PLANS	☐	(Other)			
(Other)				(Note: Report results of multiple completions on Well Completion or Recapturing Report and Log form.)			

REMARKS PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give azimuthal bearings and measured and true vertical depths for all markers and given parts down to this work.)

- 2/12/91 RU Schlumberger & ran CBL, TOC outside 5 $\frac{1}{2}$ " csg @ 1250', PBTD 2895', RU Real Well Service, SION.
- 2/13/91 TIH w/abrazijet, SN & 2 3/8" tbq, abrazijet slots @ 2696.5' & 2706', reverse sand out of hole to 2793', TOH, TIH w/pkr & tbq, set pkr @ 2635', swab hole dry in 3 runs, SD 15 min, unseat pkr, spot 8 bbls acid to end tbq, pull pkr to 2630' & then set @ 2635', formation broke @ 2260 psi, acidized w/1000 gals 15% HCl, AIR-3 BPM @ 1050, FPIP-1080, ISIP-840, @ 5 min-690, @ 10 min-660, @ 15 min-610, flow well dn & swabbed, no fluid entry, SION.
- 2/14/91 TP-0, some gas, slight show, FL 800' FSN, swabbed dn in 2 runs, RU DS & fraced w/12000 gals 30# XL containing 18000# 20/40 & 7200# 12/20, AIR-8 BPM @ 1370 psi, FPIP-1460, ISIP-920, @ 5 min-870, @ 10 min-840, @ 15 min-820, SION.
- 2/15/91 TP-0, swabbing thru pkr.

I hereby certify that the foregoing is true and correct

SIGNED Cathy Batley Seely TITLE Drilling Technician DATE 2/18/91

(This space for Field or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

SJS