

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLI
(Other instructions on
reverse side)

E*
re

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

457

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR	9. WELL NO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH
	13. STATE

Fortson Oil Company
301 Commerce St., Suite 3301, Ft. Worth, TX 76102
1980' FNL & 660' FWL, ~~1980'~~ Unit letter E.
3262 GR, 3285 KB
Eddy Co. NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input checked="" type="checkbox"/> P/A STRAWN, Compl. BS.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	<input type="checkbox"/>

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Run and set a CIBP at appx. 10,570' KB. Dump 35 feet of cement on CIBP.
Perforate four holes at appx. 6100' KB; run and set an SVEZ cement retainer at appx. 6050' KB.
Squeeze perforations with 100 sx. H Poz w/0.5% Halad 9.
Perforate four holes at appx. 5600' KB; set an SVEZ retainer at appx. 5550' KB.
Squeeze perforations with 100 sx. H Poz w/0.5% Halad 9.
Drill top retainer and cement; clean out to bottom retainer. Presssure test squeeze.
Perforate Brushy Canyon from 5,869' to 5,903' KB with two shots per foot.
Fracture treat down casing-tubing annulus.
Flow as directed and/or swab to test.

*WORK TO BEGIN 7/15/92

18. I hereby certify that the foregoing is true and correct

SIGNED James F. O'Brien TITLE CONSULTING ENGR DATE 7/14/92

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 7/17/92

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side